




# Access Compliance Report Public Rights-of-Way (Curb Ramps)



|                                         |                    |                        |                                         |                 |     |
|-----------------------------------------|--------------------|------------------------|-----------------------------------------|-----------------|-----|
| Main Street: BOW_PL                     |                    | Cross Street: BOW_PL   |                                         | Location:       | NE  |
| ADA ID: RPAT211022151315                | Ramp Type: No Ramp | Initial Pass/Fail: N/A | Overall Compliance: No                  | Severity Score: | 100 |
| Codes/Mitigation Info/Possible Solution |                    |                        | Field Measurements/Component Compliance |                 |     |



Possible Solutions:

**Provide Curb Ramp**

Surveyor Notes:

**N/A**

OC Std/PROW:

**STD 1115**

Total Cost:

\$ 3080

Parcel ID Number

**395-434-06**

Ramp Island Or Median

**N/A**

Ramp Orientation

**N/A**

Google Street View Link:

[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.77022921,-117.81372501](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.77022921,-117.81372501)

Street 1 Name

**BOW\_PL**

Stop Condition-Street 1

**N/A**

Street 2 Name

**BOW\_PL**

Stop Condition-Street 2

**N/A**

| Compliance | Description | Data | Compliance | Description | Data |
|------------|-------------|------|------------|-------------|------|
|------------|-------------|------|------------|-------------|------|

