

Access Compliance Report Public Rights-of-Way (Curb Ramps)



SW

Main Street: LEAFWOOD LN Cross Street: E SANTA CLARA AVE

Location:

ADA ID: RPAT211026095230

Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass

Overall Compliance: No

Severity Score:

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, STD 1115

Total Cost: \$ 6412

Parcel ID Number	395-366-03
Ramp Island Or Median	None
Ramp Orientation	Diag
Google Street View Link:	

Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2
Stop Condition-Street 2
StopSign

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.76683318,-117.81336368

Obstruction and Utility Measurement/Component Compliance

Compliance Description Data		Compliance Description	Data
Yes Obstructions Present?	No	N/A Utilities Present?	No
Obstruction Types	N/A	Utility Types	
Obstruction Dimensions	N/A		N/A



Field Measurements/Component Compliance									
1	Compliance Description		Data	Data Compliance Description		Data			
	N/A	Ramp Length (in)	172	N/A	Flare Ty	pe LT			
	Yes	Ramp Width (in)	48				Sloped		
	Yes	Ramp Run Slope (%)	7.5	N/A	Flare Slo	ppe LT (%)	4.6		
	Yes	Ramp Cross Slope (%)	8.0	N/A	Flare Tra	aversable LT	No		
	N/A	Landing Present	Yes	N/A	Flare Ty	pe RT			
	N/A	Landing Length (in)	49				Sloped		
	No	Landing Width (in)	46	N/A	Flare Slo	ppe RT (%)	8.5		
	No	Landing Run Slope (%)	2.7	N/A	Flare Tra	aversable RT	No		
	Yes	Landing Cross Slope (%)	1.5	Yes	DWS Pro	ovided	Yes		
	N/A	Landing Movement Obstructed?	No	Yes	DWS Co	ontrast	Yes		
		Landing Movement Type	N/A	Yes	DWS Le	ngth (in)	36		
	N/A	Landing Shared	No	Yes	DWS Fu	ll Width	Yes		
	N/A	Clear Space	Yes	Yes	DWS Of	fset Left (in)	0		
	N/A	Clear Space To Crosswalk (in)	48	Yes	DWS Of	fset Right (in)	N/A		
2	N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	No		
		Crossing 1 Direction	SE		Crossing	2 Direction	NE		
١		Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A		
า	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp In	side Crosswalk 2	N/A		
≣		Crossing 1 Slope (%)	3		Crossing	g 2 Slope (%)	0.5		
n		Crossing 1 Cross Slope (%)	0.9		Crossing	g 2 Cross Slope (%)	3.8		
	Yes	Gutter Ponding	No	No	Curb Slo	ppe	10.2		
	Yes	Gutter Lip Height (in)	0		Road Ru	un Slope (%)	1.6		
	Yes	Gutter Run Slope (%)	1.5		Road Cr	oss Slope (%)	1.2		
<u>a</u>	No	Gutter Cross Slope (%)	2.6						
י ו	Yes	s Overall Surface Condition: Acceptable		Yes	Perp Joi	nt Present	Yes		
		Cross Gutter Present?	Yes		Spandre	I Present?	Yes		
١,		Replace Cross Gutter?	No		Replace	Spandrel?	No		