




# Access Compliance Report Public Rights-of-Way (Curb Ramps)



|                                         |                    |                           |                                         |                 |     |
|-----------------------------------------|--------------------|---------------------------|-----------------------------------------|-----------------|-----|
| Main Street: TUBEROSE_ST                |                    | Cross Street: TUBEROSE_ST |                                         | Location:       | NE  |
| ADA ID: RPAT211029131747                | Ramp Type: No Ramp | Initial Pass/Fail: N/A    | Overall Compliance: No                  | Severity Score: | 100 |
| Codes/Mitigation Info/Possible Solution |                    |                           | Field Measurements/Component Compliance |                 |     |



Possible Solutions:

Provide Curb Ramp

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost:

\$ 3080

Parcel ID Number

741-131-39

Ramp Island Or Median

N/A

Ramp Orientation

N/A

Google Street View Link:

[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.54492957,-117.63525709](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.54492957,-117.63525709)

Street 1 Name

TUBEROSE\_ST

Stop Condition-Street 1

N/A

Street 2 Name

TUBEROSE\_ST

Stop Condition-Street 2

N/A

| Compliance | Description | Data | Compliance | Description | Data |
|------------|-------------|------|------------|-------------|------|
|------------|-------------|------|------------|-------------|------|

