




Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: TERRASTAR_LN		Cross Street: TERRASTAR_LN		Location:	SE
ADA ID: RPAT211101094016	Ramp Type: No Ramp	Initial Pass/Fail: N/A	Overall Compliance: No	Severity Score:	100
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		



Possible Solutions:

Provide Curb Ramp

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost:

\$ 3080

Compliance	Description	Data	Compliance	Description	Data
------------	-------------	------	------------	-------------	------

Parcel ID Number 759-452-13

Ramp Island Or Median N/A

Ramp Orientation N/A

Google Street View Link:

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.55785511,-117.63413012

Street 1 Name TERRASTAR_LN

Stop Condition-Street 1 N/A

Street 2 Name TERRASTAR_LN

Stop Condition-Street 2 N/A

