

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

 Main Street: TRUMPET_VINE_ST
 Cross Street: TRUMPET_VINE_ST
 Location:
 SW

 ADA ID: RPAT211102112957
 Ramp Type: No Ramp
 Initial Pass/Fail: N/A
 Overall Compliance: No
 Severity Score:
 100

Compliance Description

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Data Compliance

Description



Possible Solutions:

Provide Curb Ramp

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost:

tal Cost: \$

Parcel ID Number
Ramp Island Or Median
Ramp Orientation
Google Street View Link:

759-513-07 Street 1 Name

N/A Stop Condition-Street 1

N/A Street 2 Name

Stop Condition-Street 2

TRUMPET_VINE_ST N/A

3080

N/A

TRUMPET_VINE_ST

 $\underline{http://www.google.com/maps/@?api=1\&map_action=pano\&viewpoint=33.5527516,-117.63333134}$

