

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data


Main Street: STRATHMORE **Cross Street: STRATHMORE** Location: SE ADA ID: RPAT211103154308 Ramp Type: No Ramp Initial Pass/Fail: N/A **Overall Compliance: No Severity Score:** 100

Compliance Description

**Codes/Mitigation Info/Possible Solution** 

**Field Measurements/Component Compliance** Data Compliance

Description



Possible Solutions:

**Provide Curb Ramp** 

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost: 3080

Parcel ID Number Ramp Island Or Median Ramp Orientation Google Street View Link:

**759-291-22** Street 1 Name Stop Condition-Street 1 Street 2 Name

Stop Condition-Street 2

STRATHMORE

N/A

**STRATHMORE** 

N/A

http://www.google.com/maps/@?api=1&map\_action=pano&viewpoint=33.56209774,-117.63965042

