




# Access Compliance Report Public Rights-of-Way (Curb Ramps)



|                                         |                    |                              |                                         |                 |     |
|-----------------------------------------|--------------------|------------------------------|-----------------------------------------|-----------------|-----|
| Main Street: WELDON_HEIGHTS             |                    | Cross Street: WELDON_HEIGHTS |                                         | Location:       | SE  |
| ADA ID: RPAT211104132736                | Ramp Type: No Ramp | Initial Pass/Fail: N/A       | Overall Compliance: No                  | Severity Score: | 100 |
| Codes/Mitigation Info/Possible Solution |                    |                              | Field Measurements/Component Compliance |                 |     |



Possible Solutions:

Provide Curb Ramp

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost:

\$ 3080

Parcel ID Number 759-471-47

Ramp Island Or Median N/A

Ramp Orientation N/A

Google Street View Link:

[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.56345409,-117.63790553](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.56345409,-117.63790553)

Street 1 Name WELDON\_HEIGHTS

Stop Condition-Street 1 N/A

Street 2 Name WELDON\_HEIGHTS

Stop Condition-Street 2 N/A

| Compliance | Description | Data | Compliance | Description | Data |
|------------|-------------|------|------------|-------------|------|
|------------|-------------|------|------------|-------------|------|

