




Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: WELDON HEIGHTS		Cross Street: WELDON HEIGHTS		Location:	SW
ADA ID: RPAT211104141305	Ramp Type: No Ramp	Initial Pass/Fail: N/A	Overall Compliance: No	Severity Score:	100
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		



Possible Solutions:

Provide Curb Ramp

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost: \$ 3080

Parcel ID Number 759-471-48
Ramp Island Or Median N/A
Ramp Orientation N/A
Google Street View Link:

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.5631112,-117.63784289

Street 1 Name WELDON HEIGHTS
Stop Condition-Street 1 N/A
Street 2 Name WELDON HEIGHTS
Stop Condition-Street 2 N/A

Compliance	Description	Data	Compliance	Description	Data

