

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: FILLMORE DR **Cross Street: FORTNEY DR** Location: NW

ADA ID: RPAT211124135938 Ramp Type: Type 4 - Parallel **Initial Pass/Fail: Pass Overall Compliance: No Severity Score:** 6

Codes/Mitigation Info/Possible Solution



Possible Solutions: Remove & Replace Landing. Remove & Replace

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2-Perp, R304.3.2-Para, R304.5.4, STD 1115

Total Cost: \$ 783

Parcel ID Number	131-192-25
Ramp Island Or Median	None
Ramp Orientation	Diag
Google Street View Link:	

Street 1 Name FILLMORE DR Stop Condition-Street 1 **NoControl** FORTNEY_DR Street 2 Name Stop Condition-Street 2 NoControl

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.78989713,-117.98712372

Obstruction and Utility Measurement/Component Compliance

Com	pliance Description	Data	Com	oliance Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A	l		N/A



Field Measurements/Component Compliance								
- 1	Compliance Description		Data	Com	pliance Description	Data		
	N/A	Ramp Length LT (in)	89	N/A	Ramp Length RT (in)	120		
	Yes	Ramp Width LT (in)	61	Yes	Ramp Width RT (in)	61		
	Yes	Ramp Run Slope LT (%)	5.6	Yes	Ramp Run Slope RT (%)	7.9		
	Yes	Ramp Cross Slope LT (%)	1.1	Yes	Ramp Cross Slope RT (%)	0.2		
	N/A	Landing Present	Yes	Yes	DWS Provided	Yes		
	N/A	Landing Length (in)	62	Yes	DWS Contrast	Yes		
	Yes	Landing Width (in)	48	Yes	DWS Length (in)	36		
	No	Landing Run Slope (%)	2.6	Yes	DWS Full Width	Yes		
	Yes	Landing Cross Slope (%)	0.8		DWS Offset Type	Single		
	N/A	Landing Movement Obstructed?	No	Yes	DWS Offset Left (in)	0		
		Landing Movement Type	Curb	Yes	DWS Offset Right (in)	N/A		
	N/A	Landing Shared	No					
	N/A	Clear Space	Yes					
	N/A	Clear Space To Crosswalk (in)	48					
33	N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	No		
		Crossing 1 Direction	S		Crossing 2 Direction	E		
R		Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A		
ol	N/A	Ramp Inside Crosswalk 1	N/A	N/A	Ramp Inside Crosswalk 2	N/A		
R		Crossing 1 Slope (%)	6.8		Crossing 2 Slope (%)	1.3		
ol		Crossing 1 Cross Slope (%)	0.3		Crossing 2 Cross Slope (%)	1.9		
	Yes	Gutter Ponding	No	Yes	Curb Slope	1.8		
	Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	1.4		
	No	Gutter Run Slope (%)	10.5		Road Cross Slope (%)	2.3		
ta_	Yes	Gutter Cross Slope (%)	1.6	Yes	Perpendicular Joint Present	Yes		
lo	Yes	Overall Surface Condition Accep	ptable					
		Cross Gutter Present?	Yes		Spandrel Present?	Yes		
Α		Replace Cross Gutter?	No		Replace Spandrel?	No		