



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: ORANGE_OLIVE_RD Cross Street: LINCOLN_AVE Location: SW

ADA ID: RPAT220127101729 Ramp Type: Type 7 - Directional 2 Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 24

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Entire Ramp. Remove & Replace Gutter.

Surveyor Notes:

N/A

OC Std/PROW:

R304.5.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.4, STD 1115

Total Cost: \$ 3332

Parcel ID Number 000
Ramp Island Or Median ConcMed
Ramp Orientation NonDiag
Google Street View Link:

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.83603159,-117.8465393

Street 1 Name ORANGE_OLIVE_RD
Stop Condition-Street 1 Signal
Street 2 Name LINCOLN_AVE
Stop Condition-Street 2 N/A

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	38	N/A	Flare Type LT	
Yes	Ramp Width (in)	48			None
Yes	Ramp Run Slope (%)	4.8	N/A	Flare Slope LT (%)	N/A
No	Ramp Cross Slope (%)	5.7	N/A	Flare Traversable LT	N/A
Yes	Grade Break	Yes	N/A	Flare Type RT	
Yes	Grade Break Slope (%)	1.7			Curbed2
Yes	Grade Break Cross Slope (%)	1.1	N/A	Flare Slope RT (%)	N/A
	Addl Para Ramp Left?	No	N/A	Flare Traversable RT	N/A
	Addl Para Ramp Right?	No	Yes	DWS Provided	Yes
N/A	Landing Present	Yes	Yes	DWS Contrast	Yes
Yes	Landing Length (in)	52	Yes	DWS Length (in)	38
No	Landing Width (in)	46	Yes	DWS Full Width	Yes
No	Landing Run Slope (%)	4.1		DWS Offset Type	Single
No	Landing Cross Slope (%)	2.7	Yes	DWS Left Offset (in)	0
N/A	Landing Movement Obstructed?	No	N/A	DWS Right Offset (in)	0
	Landing Movement Type	N/A			
N/A	Landing Shared	Yes			
N/A	Marked Crosswalk 1	Yes	N/A	Clear Space	N/A
	Crossing 1 Direction	E	N/A	Clear Space To Crosswalk (in)	N/A
	Marked Crosswalk 1 Width (in)	128			
Yes	Ramp Inside Crosswalk 1	Yes			
	Crossing 1 Slope (%)	5.5			
	Crossing 1 Cross Slope (%)	7.2			
Yes	Gutter Ponding	No	N/A	Curb Slope	18.7
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	N/A
No	Gutter Run Slope (%)	7.3		Road Cross Slope (%)	N/A
No	Gutter Cross Slope (%)	6.6		Parallel Ramp Side	Left
Yes	Overall Surface Condition	Acceptable	Yes	Perp Joint Present	Yes
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	N/A		Replace Spandrel?	N/A

