




Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: AUGUSTA_DR		Cross Street: MOEN_ST		Location:	S
ADA ID: RPAT220201113219	Ramp Type: No Ramp	Initial Pass/Fail: N/A	Overall Compliance: No	Severity Score:	100
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		

		Possible Solutions:			
		Provide Curb Ramp			
		Surveyor Notes:			
		N/A			
		OC Std/PROW:			
		STD 1115			
		Total Cost:		\$ 3080	
Parcel ID Number		126-492-01	Street 1 Name		AUGUSTA_DR
Ramp Island Or Median		N/A	Stop Condition-Street 1		N/A
Ramp Orientation		N/A	Street 2 Name		MOEN_ST
Google Street View Link:		Stop Condition-Street 2		N/A	
		http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.80524912,-117.98008587			
					