



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: OSO_PKWY		Cross Street: OSO_PKWY		Location: S
ADA ID: RPAT220208111023	Ramp Type: No Ramp	Initial Pass/Fail: N/A	Overall Compliance: No	Severity Score: 100
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance		



Possible Solutions:

Provide Curb Ramp

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost: \$ **3080**

Parcel ID Number	779-211-01	Street 1 Name	OSO_PKWY
Ramp Island Or Median	N/A	Stop Condition-Street 1	N/A
Ramp Orientation	N/A	Street 2 Name	OSO_PKWY
Google Street View Link:		Stop Condition-Street 2	N/A

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.58936908,-117.59914908

Compliance	Description	Data	Compliance	Description	Data

