



# Access Compliance Report Public Rights-of-Way (Curb Ramps)



**Main Street:** ANTONIO\_PKWY      **Cross Street:** N/A      **Location:** W

**ADA ID:** RPAT220208130010      **Ramp Type:**Type 1 - Perpendicular Diagonal Initial Pass/Fail: Fail      **Overall Compliance:** No      **Severity Score:** 16

### Codes/Mitigation Info/Possible Solution

### Field Measurements/Component Compliance



**Possible Solutions:**

**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.**

**Surveyor Notes:**

N/A

**OC Std/PROW:**

**R204.3, R304.5.3, R302.7, STD 1115**

**Total Cost: \$ 6160**

Parcel ID Number: **787-271-01**  
 Ramp Island Or Median: **None**  
 Ramp Orientation: **Diag**  
 Google Street View Link:  
[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.58547944,-117.63045395](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.58547944,-117.63045395)

Street 1 Name: **ANTONIO\_PKWY**  
 Stop Condition-Street 1: **NoControl**  
 Street 2 Name: **N/A**  
 Stop Condition-Street 2: **StopSign**

### Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	116	N/A	Flare Type LT	
Yes	Ramp Width (in)	52			N/A
Yes	Ramp Run Slope (%)	8.02	N/A	Flare Slope LT (%)	N/A
No	Ramp Cross Slope (%)	2.2	N/A	Flare Traversable LT	N/A
N/A	Landing Present	N/A	N/A	Flare Type RT	
N/A	Landing Length (in)	N/A			N/A
N/A	Landing Width (in)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Landing Run Slope (%)	N/A	N/A	Flare Traversable RT	N/A
N/A	Landing Cross Slope (%)	N/A	N/A	DWS Provided	N/A
N/A	Landing Movement Obstructed?	N/A	N/A	DWS Contrast	N/A
	Landing Movement Type	N/A	N/A	DWS Length (in)	N/A
N/A	Landing Shared	N/A	N/A	DWS Full Width	N/A
N/A	Clear Space	Yes	N/A	DWS Offset Left (in)	N/A
N/A	Clear Space To Crosswalk (in)	N/A	N/A	DWS Offset Right (in)	N/A
N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	No
	Crossing 1 Direction	SE		Crossing 2 Direction	NE
	Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A
N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp Inside Crosswalk 2	N/A
	Crossing 1 Slope (%)	1.6		Crossing 2 Slope (%)	4.2
	Crossing 1 Cross Slope (%)	2.08		Crossing 2 Cross Slope (%)	2.42
N/A	Gutter Ponding	N/A	N/A	Curb Slope	1.4
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	2.42
N/A	Gutter Run Slope (%)	N/A		Road Cross Slope (%)	3.4
N/A	Gutter Cross Slope (%)	N/A			
No	Overall Surface Condition:	Poor	No	Perp Joint Present	No
	Cross Gutter Present?	Yes		Spandrel Present?	Yes
	Replace Cross Gutter?	No		Replace Spandrel?	No

