



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: N/A Cross Street: 17TH_ST Location: SW

ADA ID: RPAT220222143150 Ramp Type: Type 1 - Perpendicular Diagonal Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 2

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, R304.5.3, STD 1115

Total Cost: \$ 6160

Parcel ID Number 401-051-55
Ramp Island Or Median None
Ramp Orientation Diag
Google Street View Link:

Street 1 Name N/A
Stop Condition-Street 1 Signal
Street 2 Name 17TH_ST
Stop Condition-Street 2 Signal

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.75966333,-117.81196672

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	74	N/A	Flare Type LT	
Yes	Ramp Width (in)	49			Sloped
Yes	Ramp Run Slope (%)	5.5	N/A	Flare Slope LT (%)	8.4
No	Ramp Cross Slope (%)	3.1	N/A	Flare Traversable LT	No
N/A	Landing Present	Yes	N/A	Flare Type RT	
N/A	Landing Length (in)	57			Sloped
N/A	Landing Width (in)	49	N/A	Flare Slope RT (%)	7.1
N/A	Landing Run Slope (%)	0.7	N/A	Flare Traversable RT	No
N/A	Landing Cross Slope (%)	2.5	N/A	DWS Provided	Yes
N/A	Landing Movement Obstructed?	No	N/A	DWS Contrast	Yes
	Landing Movement Type	N/A	N/A	DWS Length (in)	36
N/A	Landing Shared	No	N/A	DWS Full Width	Yes
N/A	Clear Space	Yes	N/A	DWS Offset Left (in)	0
N/A	Clear Space To Crosswalk (in)	36	N/A	DWS Offset Right (in)	N/A
N/A	Marked Crosswalk 1	Yes	N/A	Marked Crosswalk 2	Yes
	Crossing 1 Direction	E		Crossing 2 Direction	N
	Marked Crosswalk 1 Width (in)	112		Marked Crosswalk 2 Width (in)	112
N/A	Ramp Inside Crosswalk 1	Yes	Yes	Ramp Inside Crosswalk 2	Yes
	Crossing 1 Slope (%)	1.7		Crossing 2 Slope (%)	2.1
	Crossing 1 Cross Slope (%)	3.2		Crossing 2 Cross Slope (%)	3
N/A	Gutter Ponding	No	No	Curb Slope	7.2
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	2.9
N/A	Gutter Run Slope (%)	3.2		Road Cross Slope (%)	1.1
N/A	Gutter Cross Slope (%)	3.8			
Yes	Overall Surface Condition: Acceptable		Yes	Perp Joint Present	Yes
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	N/A		Replace Spandrel?	N/A

