



# Access Compliance Report Public Rights-of-Way (Curb Ramps)



**Main Street: KATELLA\_AVE** **Cross Street: RUSTIC\_LN** **Location: NE**

**ADA ID: RPRK210921112036** **Ramp Type: Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass** **Overall Compliance: No** **Severity Score: 4**

**Codes/Mitigation Info/Possible Solution** **Field Measurements/Component Compliance**



**Possible Solutions:**  
Remove & Replace Landing. Remove & Replace Gutter.

**Surveyor Notes:**  
N/A

**OC Std/PROW:**  
R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R302.7, STD 1115

**Total Cost:** \$ 783

**Parcel ID Number:** 127-553-15  
**Ramp Island Or Median:** None  
**Ramp Orientation:** Diag  
**Google Street View Link:**  
[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.80321028,-117.97354557](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.80321028,-117.97354557)

**Street 1 Name:** KATELLA\_AVE  
**Stop Condition-Street 1:** NoControl  
**Street 2 Name:** RUSTIC\_LN  
**Stop Condition-Street 2:** StopSign

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	102	N/A	Flare Type LT	
Yes	Ramp Width (in)	48			Sloped
Yes	Ramp Run Slope (%)	1.5	Yes	Flare Slope LT (%)	8.6
Yes	Ramp Cross Slope (%)	0.9	N/A	Flare Traversable LT	Yes
N/A	Landing Present	Yes	N/A	Flare Type RT	
N/A	Landing Length (in)	36			Sloped
Yes	Landing Width (in)	48	N/A	Flare Slope RT (%)	11.2
No	Landing Run Slope (%)	2.3	N/A	Flare Traversable RT	No
No	Landing Cross Slope (%)	2.2	Yes	DWS Provided	Yes
N/A	Landing Movement Obstructed?	Yes	Yes	DWS Contrast	Yes
	Landing Movement Type	Bushes	Yes	DWS Length (in)	36
N/A	Landing Shared	No	Yes	DWS Full Width	Yes
N/A	Clear Space	Yes	Yes	DWS Offset Left (in)	0
N/A	Clear Space To Crosswalk (in)	48	Yes	DWS Offset Right (in)	N/A
N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	No
	Crossing 1 Direction	S		Crossing 2 Direction	E
	Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A
N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp Inside Crosswalk 2	N/A
	Crossing 1 Slope (%)	0.6		Crossing 2 Slope (%)	4.9
	Crossing 1 Cross Slope (%)	0.4		Crossing 2 Cross Slope (%)	1.6
No	Gutter Ponding	Yes	Yes	Curb Slope	3.5
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	0.9
Yes	Gutter Run Slope (%)	0.5		Road Cross Slope (%)	0.4
No	Gutter Cross Slope (%)	3.5			
Yes	Overall Surface Condition:	Acceptable	Yes	Perp Joint Present	Yes
	Cross Gutter Present?	Yes		Spandrel Present?	Yes
	Replace Cross Gutter?	No		Replace Spandrel?	No

**Obstruction and Utility Measurement/Component Compliance**

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A

