



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: MAGNOLIA_AVE **Cross Street:** KATELLA_AVE **Location:** NE

ADA ID: RPRK210921121204 **Ramp Type:**Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass **Overall Compliance:** No **Severity Score:** 0

Codes/Mitigation Info/Possible Solution **Field Measurements/Component Compliance**



Possible Solutions:
Remove & Replace Landing. Gutter Ponding Observed.

Surveyor Notes:
 N/A

OC Std/PROW:
 R304.2.2-Perp, R304.3.2-Para, R302.7, STD 1115

Total Cost: \$ 783

Parcel ID Number: 127-621-10
Ramp Island Or Median: None
Ramp Orientation: Diag
Google Street View Link:
http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.80325428,-117.97549134

Street 1 Name: MAGNOLIA_AVE
Stop Condition-Street 1: Signal
Street 2 Name: KATELLA_AVE
Stop Condition-Street 2: Signal

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	115	N/A	Flare Type LT	
Yes	Ramp Width (in)	48			Sloped
Yes	Ramp Run Slope (%)	5.1	N/A	Flare Slope LT (%)	6.1
Yes	Ramp Cross Slope (%)	1.1	N/A	Flare Traversable LT	No
N/A	Landing Present	Yes	N/A	Flare Type RT	
N/A	Landing Length (in)	48			Sloped
Yes	Landing Width (in)	48	N/A	Flare Slope RT (%)	7.3
No	Landing Run Slope (%)	2.6	N/A	Flare Traversable RT	No
Yes	Landing Cross Slope (%)	1.7	Yes	DWS Provided	Yes
N/A	Landing Movement Obstructed?	No	Yes	DWS Contrast	Yes
	Landing Movement Type	N/A	Yes	DWS Length (in)	36
N/A	Landing Shared	No	Yes	DWS Full Width	Yes
Yes	Clear Space	Yes	Yes	DWS Offset Left (in)	0
Yes	Clear Space To Crosswalk (in)	48	Yes	DWS Offset Right (in)	N/A
N/A	Marked Crosswalk 1	Yes	N/A	Marked Crosswalk 2	Yes
	Crossing 1 Direction	W		Crossing 2 Direction	S
	Marked Crosswalk 1 Width (in)	120		Marked Crosswalk 2 Width (in)	120
Yes	Ramp Inside Crosswalk 1	Yes	Yes	Ramp Inside Crosswalk 2	Yes
	Crossing 1 Slope (%)	0.6		Crossing 2 Slope (%)	1
	Crossing 1 Cross Slope (%)	2.8		Crossing 2 Cross Slope (%)	3.8
No	Gutter Ponding	Yes	Yes	Curb Slope	3
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	3.9
Yes	Gutter Run Slope (%)	0.1		Road Cross Slope (%)	0.3
Yes	Gutter Cross Slope (%)	2.8			
Yes	Overall Surface Condition: Acceptable		Yes	Perp Joint Present	Yes
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	N/A		Replace Spandrel?	N/A

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A

