



# Access Compliance Report Public Rights-of-Way (Curb Ramps)



**Main Street:** MAC\_ST **Cross Street:** REGAL\_AVE **Location:** NE

**ADA ID:** RPRK210921144305 **Ramp Type:**Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass **Overall Compliance:** No **Severity Score:** 10

Codes/Mitigation Info/Possible Solution	Field Measurements/Component Compliance
---	---



**Possible Solutions:**  
Install Landing. Remove & Replace Gutter.

**Surveyor Notes:**  
N/A

**OC Std/PROW:**  
R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, STD 1115

**Total Cost:** \$ 783

**Parcel ID Number:** 126-502-06  
**Ramp Island Or Median:** None  
**Ramp Orientation:** Diag  
**Google Street View Link:**  
[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.80401622,-117.97930479](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.80401622,-117.97930479)

**Street 1 Name:** MAC\_ST  
**Stop Condition-Street 1:** NoControl  
**Street 2 Name:** REGAL\_AVE  
**Stop Condition-Street 2:** NoControl

**Obstruction and Utility Measurement/Component Compliance**

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	51	N/A	Flare Type LT	
Yes	Ramp Width (in)	48			Sloped
Yes	Ramp Run Slope (%)	6.8	N/A	Flare Slope LT (%)	4.6
Yes	Ramp Cross Slope (%)	0.1	N/A	Flare Traversable LT	No
N/A	Landing Present	No	N/A	Flare Type RT	
N/A	Landing Length (in)	N/A			Sloped
No	Landing Width (in)	N/A	N/A	Flare Slope RT (%)	6.3
No	Landing Run Slope (%)	N/A	N/A	Flare Traversable RT	No
No	Landing Cross Slope (%)	N/A	Yes	DWS Provided	Yes
N/A	Landing Movement Obstructed?	Yes	Yes	DWS Contrast	Yes
	Landing Movement Type	Curb	Yes	DWS Length (in)	36
N/A	Landing Shared	N/A	Yes	DWS Full Width	Yes
N/A	Clear Space	Yes	Yes	DWS Offset Left (in)	0
N/A	Clear Space To Crosswalk (in)	48	Yes	DWS Offset Right (in)	N/A
N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	No
	Crossing 1 Direction	W		Crossing 2 Direction	S
	Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A
N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp Inside Crosswalk 2	N/A
	Crossing 1 Slope (%)	4.7		Crossing 2 Slope (%)	0.5
	Crossing 1 Cross Slope (%)	1.7		Crossing 2 Cross Slope (%)	2.6
Yes	Gutter Ponding	No	Yes	Curb Slope	4
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	1.3
Yes	Gutter Run Slope (%)	0.5		Road Cross Slope (%)	0.9
No	Gutter Cross Slope (%)	4.1			
Yes	Overall Surface Condition: <b>Acceptable</b>		Yes	Perp Joint Present	Yes
	Cross Gutter Present?	Yes		Spandrel Present?	Yes
	Replace Cross Gutter?	No		Replace Spandrel?	No

