



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: GUINIDA_LN		Cross Street: FLORIN_LN		Location:	SE
ADA ID: RPRK210924124127	Ramp Type: No Ramp	Initial Pass/Fail: N/A	Overall Compliance: No	Severity Score:	100
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		



Possible Solutions:

Provide Curb Ramp

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost:

\$ 3080

Parcel ID Number 127-342-04
Ramp Island Or Median N/A
Ramp Orientation N/A
Google Street View Link:

Street 1 Name

GUINIDA_LN

Stop Condition-Street 1

N/A

Street 2 Name

FLORIN_LN

Stop Condition-Street 2

N/A

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.81437214,-117.96662871

Compliance	Description	Data	Compliance	Description	Data

