



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: **GUINIDA_LN** Cross Street: **MILNEBURG_ST** Location: **SW**

ADA ID: **RPRK210924125107** Ramp Type: **No Ramp** Initial Pass/Fail: **N/A** Overall Compliance: **No** Severity Score: **100**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:
Provide Curb Ramp

Surveyor Notes:
N/A

OC Std/PROW:
STD 1115

Total Cost: \$ 3080

Compliance	Description	Data	Compliance	Description	Data

Parcel ID Number: **127-353-07**

Ramp Island Or Median: **N/A**

Ramp Orientation: **N/A**

Google Street View Link:

Street 1 Name: **GUINIDA_LN**

Stop Condition-Street 1: **N/A**

Street 2 Name: **MILNEBURG_ST**

Stop Condition-Street 2: **N/A**

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.81441084,-117.96507603

