




Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: YORKSHIRE_AVE		Cross Street: MOEN_ST		Location:	SW
ADA ID: RPRK210928125024	Ramp Type: No Ramp	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score:	115
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		



Possible Solutions:

Provide Curb Ramp Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

OC Std/PROW:

R302.7, STD 1115

Total Cost: \$ 3080

Parcel ID Number	131-202-01	Street 1 Name	YORKSHIRE_AVE
Ramp Island Or Median	N/A	Stop Condition-Street 1	N/A
Ramp Orientation	N/A	Street 2 Name	MOEN_ST
Google Street View Link:		Stop Condition-Street 2	N/A

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.7924227,-117.98619733

Compliance	Description	Data	Compliance	Description	Data

