



# Access Compliance Report Public Rights-of-Way (Curb Ramps)



**Main Street:** MARYLEE\_DR      **Cross Street:** CHAPMAN\_AVE      **Location:** SE

**ADA ID:** RPRK210928180613      **Ramp Type:** Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass      **Overall Compliance:** No      **Severity Score:** 28

**Codes/Mitigation Info/Possible Solution**      **Field Measurements/Component Compliance**



**Possible Solutions:**  
**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.**

**Surveyor Notes:**  
 N/A

**OC Std/PROW:**  
**R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R304.2.3, R305, R304.5.4, STD 1115**

**Total Cost:** \$ 6412

**Parcel ID Number:** 132-483-01  
**Ramp Island Or Median:** None  
**Ramp Orientation:** Diag  
**Google Street View Link:**  
[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.78924878,-117.98404594](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.78924878,-117.98404594)

**Street 1 Name:** MARYLEE\_DR  
**Stop Condition-Street 1:** StopSign  
**Street 2 Name:** CHAPMAN\_AVE  
**Stop Condition-Street 2:** NoControl

Obstruction and Utility Measurement/Component Compliance			
Compliance	Description	Data	
Yes	Obstructions Present?	No	N/A
	Obstruction Types	N/A	
	Obstruction Dimensions	N/A	
	Utilities Present?		No
	Utility Types		
			N/A

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	120	N/A	Flare Type LT	
Yes	Ramp Width (in)	48			Sloped
Yes	Ramp Run Slope (%)	6.1	N/A	Flare Slope LT (%)	8.4
Yes	Ramp Cross Slope (%)	0.8	N/A	Flare Traversable LT	No
N/A	Landing Present	No	N/A	Flare Type RT	
N/A	Landing Length (in)	N/A			Sloped
No	Landing Width (in)	N/A	No	Flare Slope RT (%)	11.6
No	Landing Run Slope (%)	N/A	N/A	Flare Traversable RT	Yes
No	Landing Cross Slope (%)	N/A	No	DWS Provided	No
N/A	Landing Movement Obstructed?	Yes	N/A	DWS Contrast	N/A
	Landing Movement Type	Curb	N/A	DWS Length (in)	N/A
N/A	Landing Shared	N/A	N/A	DWS Full Width	N/A
N/A	Clear Space	Yes	N/A	DWS Offset Left (in)	N/A
N/A	Clear Space To Crosswalk (in)	48	N/A	DWS Offset Right (in)	N/A
N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	No
	Crossing 1 Direction	N		Crossing 2 Direction	W
	Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A
N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp Inside Crosswalk 2	N/A
	Crossing 1 Slope (%)	8.5		Crossing 2 Slope (%)	5.9
	Crossing 1 Cross Slope (%)	3.6		Crossing 2 Cross Slope (%)	1.2
Yes	Gutter Ponding	No	Yes	Curb Slope	0.9
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	3.4
No	Gutter Run Slope (%)	7.2		Road Cross Slope (%)	6.5
No	Gutter Cross Slope (%)	2.2			
Yes	Overall Surface Condition:	Acceptable	Yes	Perp Joint Present	Yes
	Cross Gutter Present?	Yes		Spandrel Present?	Yes
	Replace Cross Gutter?	No		Replace Spandrel?	No

