



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: **BOLSA_AVE** Cross Street: **JEFFERSON_ST** Location: **NW**

ADA ID: **RPRK210929133718** Ramp Type: **Type 1 - Perpendicular Diagonal** Initial Pass/Fail: **Pass** Overall Compliance: **No** Severity Score: **6**

Codes/Mitigation Info/Possible Solution **Field Measurements/Component Compliance**



Possible Solutions:
Remove & Replace Landing. Gutter Ponding Observed.

Surveyor Notes:
N/A

OC Std/PROW:
R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R302.7, STD 1115

Total Cost: **\$ 783**

Parcel ID Number	097-141-13	Street 1 Name	BOLSA_AVE
Ramp Island Or Median	None	Stop Condition-Street 1	StopSign
Ramp Orientation	Diag	Street 2 Name	JEFFERSON_ST
Google Street View Link:		Stop Condition-Street 2	NoControl

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.74482769,-117.98427911

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	97	N/A	Flare Type LT	
Yes	Ramp Width (in)	48			Sloped
Yes	Ramp Run Slope (%)	3.8	N/A	Flare Slope LT (%)	3.5
Yes	Ramp Cross Slope (%)	0.5	N/A	Flare Traversable LT	No
N/A	Landing Present	Yes	N/A	Flare Type RT	
N/A	Landing Length (in)	35			Sloped
Yes	Landing Width (in)	48	N/A	Flare Slope RT (%)	4.6
No	Landing Run Slope (%)	4.1	N/A	Flare Traversable RT	No
No	Landing Cross Slope (%)	2.8	Yes	DWS Provided	Yes
N/A	Landing Movement Obstructed?	Yes	Yes	DWS Contrast	Yes
	Landing Movement Type	Wall	Yes	DWS Length (in)	37
N/A	Landing Shared	No	Yes	DWS Full Width	Yes
N/A	Clear Space	Yes	Yes	DWS Offset Left (in)	0
N/A	Clear Space To Crosswalk (in)	48	Yes	DWS Offset Right (in)	N/A
N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	No
	Crossing 1 Direction	S		Crossing 2 Direction	E
	Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A
N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp Inside Crosswalk 2	N/A
	Crossing 1 Slope (%)	1.2		Crossing 2 Slope (%)	2.2
	Crossing 1 Cross Slope (%)	5.6		Crossing 2 Cross Slope (%)	3.8
No	Gutter Ponding	Yes	Yes	Curb Slope	1
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	0.6
Yes	Gutter Run Slope (%)	3.2		Road Cross Slope (%)	0.8
Yes	Gutter Cross Slope (%)	1.7			
Yes	Overall Surface Condition: Acceptable		Yes	Perp Joint Present	Yes
	Cross Gutter Present?	Yes		Spandrel Present?	Yes
	Replace Cross Gutter?	No		Replace Spandrel?	No

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A

