


Access Compliance Report Public Rights-of-Way (Curb Ramps)

Main Street: PURDY_ST	Cross Street: PURDY_ST	Location: S
-----------------------	------------------------	-------------

ADA ID: RPRK211005115418	Ramp Type: No Ramp	Initial Pass/Fail: N/A	Overall Compliance: No	Severity Score: 100
--------------------------	--------------------	------------------------	------------------------	---------------------

Codes/Mitigation Info/Possible Solution	Field Measurements/Component Compliance
-----------------------------------------	-----------------------------------------



Possible Solutions:
Provide Curb Ramp

Surveyor Notes:
N/A

OC Std/PROW:
STD 1115

Total Cost: \$ 3080

Compliance	Description	Data	Compliance	Description	Data

Parcel ID Number	097-332-30	Street 1 Name	PURDY_ST
Ramp Island Or Median	N/A	Stop Condition-Street 1	N/A
Ramp Orientation	N/A	Street 2 Name	PURDY_ST
Google Street View Link:		Stop Condition-Street 2	N/A

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.75052365,-117.97814236

