



# Access Compliance Report Public Rights-of-Way (Curb Ramps)



|                                         |                    |                        |                                         |                 |     |
|-----------------------------------------|--------------------|------------------------|-----------------------------------------|-----------------|-----|
| Main Street: PURDY_ST                   |                    | Cross Street: PURDY_ST |                                         | Location:       | S   |
| ADA ID: RPRK211005120727                | Ramp Type: No Ramp | Initial Pass/Fail: N/A | Overall Compliance: No                  | Severity Score: | 100 |
| Codes/Mitigation Info/Possible Solution |                    |                        | Field Measurements/Component Compliance |                 |     |



Possible Solutions:

Provide Curb Ramp

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost: \$ 3080

Parcel ID Number 097-476-03  
Ramp Island Or Median N/A  
Ramp Orientation N/A  
Google Street View Link:

Street 1 Name PURDY\_ST  
Stop Condition-Street 1 N/A  
Street 2 Name PURDY\_ST  
Stop Condition-Street 2 N/A

[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.74981205,-117.97814008](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.74981205,-117.97814008)

| Compliance | Description | Data | Compliance | Description | Data |
|------------|-------------|------|------------|-------------|------|
|            |             |      |            |             |      |

