



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: CEDARWOOD_AVE		Cross Street: CEDARWOOD_AVE		Location:	S
ADA ID: RPRK211005175413	Ramp Type: No Ramp	Initial Pass/Fail: N/A	Overall Compliance: No	Severity Score:	100
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		



Possible Solutions:

Provide Curb Ramp

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost: \$ 3080

Parcel ID Number 142-054-13
Ramp Island Or Median N/A
Ramp Orientation N/A
Google Street View Link:

Street 1 Name CEDARWOOD_AVE
Stop Condition-Street 1 N/A
Street 2 Name CEDARWOOD_AVE
Stop Condition-Street 2 N/A

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.73903324,-117.99348057

Compliance	Description	Data	Compliance	Description	Data
------------	-------------	------	------------	-------------	------

