



Access Compliance Report

Public Rights-of-Way

(Curb Ramps)



Main Street: NEWPORT_AVE Cross Street: SKYLINE_DR Location: SE

ADA ID: RPRK211007132853 Ramp Type: Type 1 - Perpendicular Diagonal Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Replace Cross Gutter.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, STD 122-2, R302.3, R402.2, STD 1115

Total Cost: \$ 8668

Parcel ID Number **502-101-45**
Ramp Island Or Median **None**
Ramp Orientation **Diag**
Google Street View Link:

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.75776009,-117.80254799

Street 1 Name **NEWPORT_AVE**
Stop Condition-Street 1 **NoControl**
Street 2 Name **SKYLINE_DR**
Stop Condition-Street 2 **StopSign**

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
No	Obstructions Present?	Yes	N/A	Utilities Present?	Yes
	Obstruction Types	Power Pole		Utility Types	
	Obstruction Dimensions	N/A		Guy Wire	

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	80	N/A	Flare Type LT	
Yes	Ramp Width (in)	48			Sloped
Yes	Ramp Run Slope (%)	7.8	N/A	Flare Slope LT (%)	4.5
Yes	Ramp Cross Slope (%)	1.7	N/A	Flare Traversable LT	Yes
N/A	Landing Present	No	N/A	Flare Type RT	
N/A	Landing Length (in)	N/A			Sloped
N/A	Landing Width (in)	N/A	N/A	Flare Slope RT (%)	1.1
N/A	Landing Run Slope (%)	N/A	N/A	Flare Traversable RT	Yes
N/A	Landing Cross Slope (%)	N/A	N/A	DWS Provided	Yes
N/A	Landing Movement Obstructed?	No	N/A	DWS Contrast	Yes
	Landing Movement Type	N/A	N/A	DWS Length (in)	36
N/A	Landing Shared	N/A	N/A	DWS Full Width	Yes
N/A	Clear Space	Yes	N/A	DWS Offset Left (in)	0
N/A	Clear Space To Crosswalk (in)	N/A	N/A	DWS Offset Right (in)	N/A
N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	No
	Crossing 1 Direction	NW		Crossing 2 Direction	SW
	Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A
N/A	Ramp Inside Crosswalk 1	N/A	No	Ramp Inside Crosswalk 2	N/A
	Crossing 1 Slope (%)	10.1		Crossing 2 Slope (%)	3.3
	Crossing 1 Cross Slope (%)	3.2		Crossing 2 Cross Slope (%)	0.2
N/A	Gutter Ponding	No	No	Curb Slope	16
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	2.3
N/A	Gutter Run Slope (%)	12.6		Road Cross Slope (%)	8.8
N/A	Gutter Cross Slope (%)	2.9			
Yes	Overall Surface Condition: Acceptable		Yes	Perp Joint Present	Yes
	Cross Gutter Present?	Yes		Spandrel Present?	Yes
	Replace Cross Gutter?	Yes		Replace Spandrel?	No

