



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: GERSHON_PL **Cross Street:** 17TH_ST **Location:** SW

ADA ID: RPRK211011134620 **Ramp Type:**Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass **Overall Compliance:** No **Severity Score:** 10

Codes/Mitigation Info/Possible Solution **Field Measurements/Component Compliance**



Possible Solutions:
Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.

Surveyor Notes:
 N/A

OC Std/PROW:
 R304.2.2, R304.2.1, R304.5.3, R304.5.4, STD 1115

Total Cost: \$ 6412

Parcel ID Number: 401-052-12
Ramp Island Or Median: None
Ramp Orientation: Diag
Google Street View Link:
http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.75978106,-117.81369106

Street 1 Name: GERSHON_PL
Stop Condition-Street 1: StopSign
Street 2 Name: 17TH_ST
Stop Condition-Street 2: NoControl

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	108	N/A	Flare Type LT	
Yes	Ramp Width (in)	48		Flare Slope LT (%)	4.8
Yes	Ramp Run Slope (%)	7.8	N/A	Flare Traversable LT	Yes
Yes	Ramp Cross Slope (%)	0.5	N/A	Flare Type RT	
N/A	Landing Present	Yes		Flare Slope RT (%)	6.5
N/A	Landing Length (in)	40	N/A	Flare Traversable RT	Yes
Yes	Landing Width (in)	48	Yes	DWS Provided	Yes
Yes	Landing Run Slope (%)	1.6	N/A	DWS Contrast	Yes
No	Landing Cross Slope (%)	2.5	Yes	DWS Length (in)	36
N/A	Landing Movement Obstructed?	No	Yes	DWS Full Width	Yes
	Landing Movement Type	N/A	Yes	DWS Offset Left (in)	0
N/A	Landing Shared	No	Yes	DWS Offset Right (in)	N/A
N/A	Clear Space	Yes	N/A	Marked Crosswalk 1	No
N/A	Clear Space To Crosswalk (in)	48	Yes	Marked Crosswalk 2	No
N/A	Marked Crosswalk 1	No		Crossing 1 Direction	E
	Crossing 1 Direction	E		Crossing 2 Direction	N
	Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A
N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp Inside Crosswalk 2	N/A
	Crossing 1 Slope (%)	6.4		Crossing 2 Slope (%)	6.8
	Crossing 1 Cross Slope (%)	0.2		Crossing 2 Cross Slope (%)	0.1
Yes	Gutter Ponding	No	No	Curb Slope	6.6
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	0.6
No	Gutter Run Slope (%)	5.8		Road Cross Slope (%)	5.7
Yes	Gutter Cross Slope (%)	0.1			
Yes	Overall Surface Condition: Acceptable		Yes	Perp Joint Present	Yes
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	N/A		Replace Spandrel?	N/A

