

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



SE

Main Street: 17TH\_ST **Cross Street: GERSHON PL**  Location:

ADA ID: RPRK211011134944

Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Fail

**Overall Compliance: No** 

**Severity Score:** 16

## **Codes/Mitigation Info/Possible Solution**



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, R304.5.3, STD 1115

Total Cost:

6160

Parcel ID Number	401-051-06
Ramp Island Or Median	None
Ramp Orientation	Diag
Google Street View Link:	

Street 1 Name 17TH\_ST Stop Condition-Street 1 **NoControl** Street 2 Name GERSHON\_PL Stop Condition-Street 2 StopSign

http://www.google.com/maps/@?api=1&map\_action=pano&viewpoint=33.75978258,-117.81351635

## **Obstruction and Utility Measurement/Component Compliance**

Com	pliance Description	Data	Com	pliance Description	<u>Data</u>
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A	J		N/A







Field Measurements/Component Compliance										
	Compliance Description		Data	Compliance Description			Data			
	N/A	Ramp Length (in)	112	N/A	Flare Ty	pe LT				
	Yes	Ramp Width (in)	48				N/A			
	No	Ramp Run Slope (%)	9.6	N/A	Flare Slo	ppe LT (%)	N/A			
	No	Ramp Cross Slope (%)	2.8	N/A	Flare Tra	aversable LT	N/A			
	N/A	Landing Present	N/A	N/A	Flare Ty	pe RT				
	N/A	Landing Length (in)	N/A				N/A			
	N/A	Landing Width (in)	N/A	N/A	Flare Slo	ope RT (%)	N/A			
	N/A	Landing Run Slope (%)	N/A	N/A	Flare Tra	aversable RT	N/A			
	N/A	Landing Cross Slope (%)	N/A	N/A	DWS Pr	ovided	N/A			
	N/A	Landing Movement Obstructed?	N/A	N/A	DWS Co	ontrast	N/A			
		Landing Movement Type	N/A	N/A	DWS Le	ngth (in)	N/A			
	N/A	Landing Shared	N/A	N/A	DWS Fu	II Width	N/A			
	N/A	Clear Space	Yes	N/A	DWS Of	fset Left (in)	N/A			
	N/A	Clear Space To Crosswalk (in)	N/A	N/A	DWS Of	fset Right (in)	N/A			
0	N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	No			
		Crossing 1 Direction	N		Crossing	g 2 Direction	w			
т		Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A			
ı	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp In	side Crosswalk 2	N/A			
ᅵ		Crossing 1 Slope (%)	8.1		Crossino	g 2 Slope (%)	5.2			
n		Crossing 1 Cross Slope (%)	0.9		Crossino	g 2 Cross Slope (%)	2.3			
	N/A	Gutter Ponding	N/A	No	Curb Slo	рре	6.7			
	Yes	Gutter Lip Height (in)	0		Road R	un Slope (%)	3.5			
	N/A	Gutter Run Slope (%)	N/A		Road Cr	oss Slope (%)	8.8			
<u>a</u>	N/A	Gutter Cross Slope (%)	N/A							
0	Yes	Overall Surface Condition: Accep	otable	Yes	Perp Joi	int Present	Yes			
		Cross Gutter Present?	No		•	l Present?	No			
4		Replace Cross Gutter?	N/A		Replace	Spandrel?	N/A			