



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: AFTON_LN Cross Street: SE_SKYLINE_DR Location: NE

ADA ID: RPRK211012112952 Ramp Type: Type 6 - Directional 1 Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 6

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Entire Ramp. Remove & Replace Gutter.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, R304.5.3, R304.5.4, STD 1115

Total Cost: \$ 3332

Parcel ID Number 502-131-01
Ramp Island Or Median None
Ramp Orientation NonDiag
Google Street View Link:

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.75404023,-117.7972187

Street 1 Name AFTON_LN
Stop Condition-Street 1 NoControl
Street 2 Name SE_SKYLINE_DR
Stop Condition-Street 2 N/A

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	165	N/A	Flare Type LT	
Yes	Ramp Width (in)	98			Sloped
Yes	Ramp Run Slope (%)	5.6	N/A	Flare Slope LT (%)	6.1
Yes	Ramp Cross Slope (%)	1.5	N/A	Flare Traversable LT	No
Yes	Grade Break	Yes	Yes	Flare Type RT	
No	Grade Break Slope (%)	5.7			Curbed2
No	Grade Break Cross Slope (%)	2.2	N/A	Flare Slope RT (%)	N/A
	Addl Para Ramp Left?	No	N/A	Flare Traversable RT	N/A
	Addl Para Ramp Right?	No	Yes	DWS Provided	Yes
N/A	Landing Present	Yes	Yes	DWS Contrast	Yes
Yes	Landing Length (in)	77	Yes	DWS Length (in)	54
Yes	Landing Width (in)	48	Yes	DWS Full Width	Yes
Yes	Landing Run Slope (%)	0.5		DWS Offset Type	Single
No	Landing Cross Slope (%)	4	Yes	DWS Left Offset (in)	0
N/A	Landing Movement Obstructed?	No	N/A	DWS Right Offset (in)	0
	Landing Movement Type	N/A			
N/A	Landing Shared	No			
N/A	Marked Crosswalk 1	No	N/A	Clear Space	N/A
	Crossing 1 Direction	SE	N/A	Clear Space To Crosswalk (in)	N/A
	Marked Crosswalk 1 Width (in)	N/A			
N/A	Ramp Inside Crosswalk 1	N/A			
	Crossing 1 Slope (%)	4.2			
	Crossing 1 Cross Slope (%)	1.7			
Yes	Gutter Ponding	No	No	Curb Slope	15.2
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	N/A
No	Gutter Run Slope (%)	6.7		Road Cross Slope (%)	N/A
Yes	Gutter Cross Slope (%)	1.1		Parallel Ramp Side	Right
Yes	Overall Surface Condition	Acceptable	Yes	Perp Joint Present	Yes
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	N/A		Replace Spandrel?	N/A

