



# Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: WYNDHAM COURT RD Cross Street: RED HILL AVE Location: S

ADA ID: RPRK211012121008 Ramp Type: Type 6 - Directional 1 Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 50

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



### Possible Solutions:

Remove & Replace Entire Ramp. Remove & Replace Gutter.

### Surveyor Notes:

N/A

### OC Std/PROW:

R304.5.3, R304.2.2-Perp, R304.3.2-Para, R304.5.2, R305, R304.5.4, STD 1115

Total Cost: \$ 3332

Parcel ID Number 502-011-13  
Ramp Island Or Median None  
Ramp Orientation NonDiag  
Google Street View Link:

[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.75752266,-117.79138995](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.75752266,-117.79138995)

Street 1 Name WYNDHAM COURT RD  
Stop Condition-Street 1 NoControl  
Street 2 Name RED HILL AVE  
Stop Condition-Street 2 N/A

## Obstruction and Utility Measurement/Component Compliance

| Compliance | Description            | Data | Compliance | Description        | Data |
|------------|------------------------|------|------------|--------------------|------|
| Yes        | Obstructions Present?  | No   | N/A        | Utilities Present? | No   |
|            | Obstruction Types      | N/A  |            | Utility Types      |      |
|            | Obstruction Dimensions | N/A  |            |                    | N/A  |

| Compliance | Description                   | Data       | Compliance | Description                   | Data    |
|------------|-------------------------------|------------|------------|-------------------------------|---------|
| N/A        | Ramp Length (in)              | 117        | Yes        | Flare Type LT                 |         |
| Yes        | Ramp Width (in)               | 80         |            |                               | Curbed2 |
| Yes        | Ramp Run Slope (%)            | 3.6        | N/A        | Flare Slope LT (%)            | N/A     |
| No         | Ramp Cross Slope (%)          | 8.9        | N/A        | Flare Traversable LT          | N/A     |
| No         | Grade Break                   | No         | N/A        | Flare Type RT                 |         |
| N/A        | Grade Break Slope (%)         | N/A        |            |                               | Sloped  |
| N/A        | Grade Break Cross Slope (%)   | N/A        | Yes        | Flare Slope RT (%)            | 5.9     |
|            | Addl Para Ramp Left?          | No         | N/A        | Flare Traversable RT          | Yes     |
|            | Addl Para Ramp Right?         | No         | No         | DWS Provided                  | No      |
| N/A        | Landing Present               | Yes        | N/A        | DWS Contrast                  | N/A     |
| Yes        | Landing Length (in)           | 119        | N/A        | DWS Length (in)               | N/A     |
| Yes        | Landing Width (in)            | 109        | N/A        | DWS Full Width                | N/A     |
| No         | Landing Run Slope (%)         | 10.3       |            | DWS Offset Type               | N/A     |
| Yes        | Landing Cross Slope (%)       | 2.9        | N/A        | DWS Left Offset (in)          | N/A     |
| N/A        | Landing Movement Obstructed?  | No         | N/A        | DWS Right Offset (in)         | N/A     |
|            | Landing Movement Type         | N/A        |            |                               |         |
| N/A        | Landing Shared                | No         |            |                               |         |
| N/A        | Marked Crosswalk 1            | No         | N/A        | Clear Space                   | N/A     |
|            | Crossing 1 Direction          | NE         | N/A        | Clear Space To Crosswalk (in) | N/A     |
| N/A        | Marked Crosswalk 1 Width (in) | N/A        |            |                               |         |
| N/A        | Ramp Inside Crosswalk 1       | N/A        |            |                               |         |
|            | Crossing 1 Slope (%)          | 6.2        |            |                               |         |
|            | Crossing 1 Cross Slope (%)    | 11.3       |            |                               |         |
| Yes        | Gutter Ponding                | No         | N/A        | Curb Slope                    | 0.6     |
| Yes        | Gutter Lip Height (in)        | 0          |            | Road Run Slope (%)            | N/A     |
| No         | Gutter Run Slope (%)          | 11.9       |            | Road Cross Slope (%)          | N/A     |
| No         | Gutter Cross Slope (%)        | 9          |            | Parallel Ramp Side            | Right   |
| Yes        | Overall Surface Condition     | Acceptable | Yes        | Perp Joint Present            | Yes     |
|            | Cross Gutter Present?         | Yes        |            | Spandrel Present?             | Yes     |
|            | Replace Cross Gutter?         | No         |            | Replace Spandrel?             | No      |

