



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: ARROYO_AVE Cross Street: LA_LOMA_DR Location: E

ADA ID: RPRK211012125922 Ramp Type: Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Landing.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2-Perp, R304.3.2-Para, R304.5.3, STD 1115

Total Cost: \$ 531

Parcel ID Number	502-021-01	Street 1 Name	ARROYO_AVE
Ramp Island Or Median	None	Stop Condition-Street 1	StopSign
Ramp Orientation	Diag	Street 2 Name	LA_LOMA_DR
Google Street View Link:		Stop Condition-Street 2	StopSign

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.76097445,-117.79360836

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	107	N/A	Flare Type LT	
Yes	Ramp Width (in)	106			Sloped
Yes	Ramp Run Slope (%)	6.2	Yes	Flare Slope LT (%)	2.5
Yes	Ramp Cross Slope (%)	1.1	N/A	Flare Traversable LT	Yes
N/A	Landing Present	Yes	Yes	Flare Type RT	
N/A	Landing Length (in)	106			Curbed2
Yes	Landing Width (in)	48	N/A	Flare Slope RT (%)	N/A
No	Landing Run Slope (%)	2.3	N/A	Flare Traversable RT	N/A
No	Landing Cross Slope (%)	2.6	Yes	DWS Provided	Yes
N/A	Landing Movement Obstructed?	No	Yes	DWS Contrast	Yes
	Landing Movement Type	N/A	Yes	DWS Length (in)	36
N/A	Landing Shared	No	Yes	DWS Full Width	Yes
Yes	Clear Space	Yes	Yes	DWS Offset Left (in)	0
Yes	Clear Space To Crosswalk (in)	48	Yes	DWS Offset Right (in)	6
N/A	Marked Crosswalk 1	Yes	N/A	Marked Crosswalk 2	Yes
	Crossing 1 Direction	NW		Crossing 2 Direction	SW
	Marked Crosswalk 1 Width (in)	120		Marked Crosswalk 2 Width (in)	144
Yes	Ramp Inside Crosswalk 1	Yes	Yes	Ramp Inside Crosswalk 2	Yes
	Crossing 1 Slope (%)	0		Crossing 2 Slope (%)	6.5
	Crossing 1 Cross Slope (%)	0		Crossing 2 Cross Slope (%)	2.7
Yes	Gutter Ponding	No	Yes	Curb Slope	1.9
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	3.7
Yes	Gutter Run Slope (%)	1.1		Road Cross Slope (%)	2.1
Yes	Gutter Cross Slope (%)	0.8			
Yes	Overall Surface Condition: Acceptable		Yes	Perp Joint Present	Yes
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	N/A		Replace Spandrel?	N/A

