




Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: NEWPORT_BLV **Cross Street:** E_SKYLARK_PL **Location:** W

ADA ID: RPRK211012144218 **Ramp Type:** Type 4 - Parallel **Initial Pass/Fail:** Fail **Overall Compliance:** No **Severity Score:** 15

Codes/Mitigation Info/Possible Solution **Field Measurements/Component Compliance**



Possible Solutions:
Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:
 N/A

OC Std/PROW:
R304.3.2, STD 1115

Total Cost: \$ 4000

Parcel ID Number: 503-742-25
Ramp Island Or Median: None
Ramp Orientation: Diag
Google Street View Link:
http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.78396651,-117.7710851

Street 1 Name: NEWPORT_BLV
Stop Condition-Street 1: NoControl
Street 2 Name: E_SKYLARK_PL
Stop Condition-Street 2: StopSign

Obstruction and Utility Measurement/Component Compliance			
Compliance	Description	Data	Compliance Description
Yes	Obstructions Present?	No	N/A Utilities Present?
	Obstruction Types	N/A	Utility Types
	Obstruction Dimensions	N/A	

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	135	N/A	Ramp Length RT (in)	114
Yes	Ramp Width LT (in)	80	Yes	Ramp Width RT (in)	77
No	Ramp Run Slope LT (%)	10.9	Yes	Ramp Run Slope RT (%)	2.5
Yes	Ramp Cross Slope LT (%)	1.1	Yes	Ramp Cross Slope RT (%)	0.2
N/A	Landing Present	N/A	N/A	DWS Provided	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Contrast	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing Run Slope (%)	N/A	N/A	DWS Full Width	N/A
N/A	Landing Cross Slope (%)	N/A		DWS Offset Type	N/A
N/A	Landing Movement Obstructed?	N/A	N/A	DWS Offset Left (in)	N/A
	Landing Movement Type	N/A	N/A	DWS Offset Right (in)	N/A
N/A	Landing Shared	N/A			
N/A	Clear Space	Yes			
N/A	Clear Space To Crosswalk (in)	N/A			
N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	No
	Crossing 1 Direction	SE		Crossing 2 Direction	NE
N/A	Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A
N/A	Ramp Inside Crosswalk 1	N/A	N/A	Ramp Inside Crosswalk 2	N/A
	Crossing 1 Slope (%)	3.3		Crossing 2 Slope (%)	4.5
	Crossing 1 Cross Slope (%)	6.6		Crossing 2 Cross Slope (%)	1.9
N/A	Gutter Ponding	N/A	N/A	Curb Slope	9.4
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	6.1
N/A	Gutter Run Slope (%)	N/A		Road Cross Slope (%)	5
N/A	Gutter Cross Slope (%)	N/A	Yes	Perpendicular Joint Present	Yes
Yes	Overall Surface Condition	Acceptable			
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	N/A		Replace Spandrel?	N/A

