



# Access Compliance Report Public Rights-of-Way (Curb Ramps)



**Main Street:** THORLEY\_RD      **Cross Street:** CORONEL\_RD      **Location:** SE

**ADA ID:** RPRK211013120924      **Ramp Type:** Type 4 - Parallel      **Initial Pass/Fail:** Fail      **Overall Compliance:** No      **Severity Score:** 2

**Codes/Mitigation Info/Possible Solution**      **Field Measurements/Component Compliance**



**Possible Solutions:**  
**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.**

**Surveyor Notes:**  
 N/A

**OC Std/PROW:**  
 R204.3, R304.5.3, STD 1115

**Total Cost:** \$ 4000

**Parcel ID Number:** 503-083-01  
**Ramp Island Or Median:** None  
**Ramp Orientation:** Diag  
**Google Street View Link:**  
[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.76763024,-117.78120501](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.76763024,-117.78120501)

**Street 1 Name:** THORLEY\_RD  
**Stop Condition-Street 1:** StopSign  
**Street 2 Name:** CORONEL\_RD  
**Stop Condition-Street 2:** NoControl

**Obstruction and Utility Measurement/Component Compliance**

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	120	N/A	Ramp Length RT (in)	129
Yes	Ramp Width LT (in)	83	Yes	Ramp Width RT (in)	100
Yes	Ramp Run Slope LT (%)	6.8	Yes	Ramp Run Slope RT (%)	1.9
No	Ramp Cross Slope LT (%)	5	No	Ramp Cross Slope RT (%)	3.1
N/A	Landing Present	N/A	N/A	DWS Provided	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Contrast	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing Run Slope (%)	N/A	N/A	DWS Full Width	N/A
N/A	Landing Cross Slope (%)	N/A		DWS Offset Type	N/A
N/A	Landing Movement Obstructed?	N/A	N/A	DWS Offset Left (in)	N/A
	Landing Movement Type	N/A	N/A	DWS Offset Right (in)	N/A
N/A	Landing Shared	N/A			
N/A	Clear Space	Yes			
N/A	Clear Space To Crosswalk (in)	N/A			
N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	No
	Crossing 1 Direction	N		Crossing 2 Direction	W
N/A	Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A
N/A	Ramp Inside Crosswalk 1	N/A	N/A	Ramp Inside Crosswalk 2	N/A
	Crossing 1 Slope (%)	9.4		Crossing 2 Slope (%)	0.4
	Crossing 1 Cross Slope (%)	2		Crossing 2 Cross Slope (%)	2.5
N/A	Gutter Ponding	N/A	N/A	Curb Slope	0.4
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	4.3
N/A	Gutter Run Slope (%)	N/A		Road Cross Slope (%)	0.8
N/A	Gutter Cross Slope (%)	N/A	No	Perpendicular Joint Present	No
Yes	Overall Surface Condition	Acceptable			
	Cross Gutter Present?	Yes		Spandrel Present?	Yes
	Replace Cross Gutter?	No		Replace Spandrel?	No

