

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: OMEGA_DR **Cross Street: BROWNING_AVE** Location: **Overall Compliance: No** ADA ID: RPRK211014115931 Ramp Type: Type 7 - Directional 2 Initial Pass/Fail: Fail **Severity Score:** 2

Codes/Mitigation Info/Possible Solution			
	Possible Solutions:		
	Remove & Replace Entire Ramp.		
9	Surveyor Notes:		
E. E. E.	N/A		
	OC Std/PROW:		
5	R304.5.3, STD 1115		
	Total Cost: \$	3	
	1		

Parcel ID Number	502-322-18	Street 1 Name	OMEGA_DR
Ramp Island Or Median	None	Stop Condition-Street 1	StopSign
Ramp Orientation	NonDiag	Street 2 Name	BROWNING_AVE
Google Street View Link:		Stop Condition-Street 2	N/A

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.75036257,-117.78745059

Obstruction and Utility Measurement/Component Compliance

Compliance Description	Data	Compliance Description	<u>Data</u>
Yes Obstructions Present?	No	N/A Utilities Present?	No
Obstruction Types	N/A	Utility Types	
Obstruction Dimensions	N/A		N/A



	Field Measurements/Component Compliance						
	Com	pliance Description	Data	Com	pliance Description	Dat	
	N/A	Ramp Length (in)	150	N/A	Flare Type LT		
	Yes	Ramp Width (in)	48			N/A	
	Yes	Ramp Run Slope (%)	6.3	N/A	Flare Slope LT (%)	N/A	
	No	Ramp Cross Slope (%)	2.2	N/A	Flare Traversable LT	N/A	
	N/A	Grade Break	N/A	N/A	Flare Type RT		
	N/A	Grade Break Slope (%)	N/A			N/A	
	N/A	Grade Break Cross Slope (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		Addl Para Ramp Left?	No	N/A	Flare Traversable RT	N/A	
		Addl Para Ramp Right?	No	N/A	DWS Provided	N/A	
	N/A	Landing Present	N/A	N/A	DWS Contrast	N/A	
	N/A	Landing Length (in)	N/A	N/A	DWS Length (in)	N/A	
	N/A	Landing Width (in)	N/A	N/A	DWS Full Width	N/A	
	N/A	Landing Run Slope (%)	N/A		DWS Offset Type	N/A	
	N/A	Landing Cross Slope (%)	N/A	N/A	DWS Left Offset (in)	N/A	
3080	N/A	Landing Movement Obstructed?	N/A	N/A	DWS Right Offset (in)	N/A	
		Landing Movement Type	N/A				
A_DR	N/A	Landing Shared	N/A				
pSign	N/A	Marked Crosswalk 1	No	N/A	Clear Space	N/A	
3_AVE		Crossing 1 Direction	SW	N/A	Clear Space To Crosswalk (in)	N/A	
N/A		Marked Crosswalk 1 Width (in)	N/A				
	N/A	Ramp Inside Crosswalk 1	N/A				
		Crossing 1 Slope (%)	4.1				
		Crossing 1 Cross Slope (%)	5.7				
Data	N/A	Gutter Ponding	N/A	N/A	Curb Slope	8.5	
No	Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	N/A	
	N/A	Gutter Run Slope (%)	N/A		Road Cross Slope (%)	N/A	
N/A	N/A	Gutter Cross Slope (%)	N/A		Parallel Ramp Side	Left	
anna H	Yes	Overall Surface Condition Acce	ptable	Yes	Perp Joint Present	Yes	
		Cross Gutter Present?	Yes		Spandrel Present?	Yes	
		Replace Cross Gutter?	No	l	Replace Spandrel?	No	