



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: SIENNA_PKWY **Cross Street:** BENJAMIN_DR **Location:** E

ADA ID: RPRK211020171400 **Ramp Type:** Type 1 - Perpendicular **Initial Pass/Fail:** Pass **Overall Compliance:** No **Severity Score:** 25

Codes/Mitigation Info/Possible Solution **Field Measurements/Component Compliance**



Possible Solutions:
Remove & Replace Entire Ramp. Remove & Replace Gutter.

Surveyor Notes:
 N/A

OC Std/PROW:
 R304.2.2, R204.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R305, R304.5.4, STD 1115

Total Cost: \$ 3332

Parcel ID Number: 759-171-25
Ramp Island Or Median: None
Ramp Orientation: NonDiag
Google Street View Link:
http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.57061425,-117.63837146

Street 1 Name: SIENNA_PKWY
Stop Condition-Street 1: YieldSign
Street 2 Name: BENJAMIN_DR
Stop Condition-Street 2: N/A

Obstruction and Utility Measurement/Component Compliance			
Compliance	Description	Data	Compliance Description
Yes	Obstructions Present?	No	N/A Utilities Present?
	Obstruction Types	N/A	Utility Types
	Obstruction Dimensions	N/A	

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	137	N/A	Flare Type LT	
Yes	Ramp Width (in)	60			Sloped
Yes	Ramp Run Slope (%)	2.9	N/A	Flare Slope LT (%)	8.9
Yes	Ramp Cross Slope (%)	0.4	N/A	Flare Traversable LT	No
N/A	Landing Present	No	N/A	Flare Type RT	
N/A	Landing Length (in)	N/A			Sloped
No	Landing Width (in)	N/A	N/A	Flare Slope RT (%)	12
No	Landing Run Slope (%)	N/A	N/A	Flare Traversable RT	No
No	Landing Cross Slope (%)	N/A	No	DWS Provided	No
N/A	Landing Movement Obstructed?	Yes	N/A	DWS Contrast	N/A
	Landing Movement Type	Curb	N/A	DWS Length (in)	N/A
N/A	Landing Shared	N/A	N/A	DWS Full Width	N/A
N/A	Clear Space	N/A	N/A	DWS Offset Left (in)	N/A
N/A	Clear Space To Crosswalk (in)	N/A	N/A	DWS Offset Right (in)	N/A
N/A	Marked Crosswalk 1	Yes	N/A	Marked Crosswalk 2	N/A
	Crossing 1 Direction	N		Crossing 2 Direction	N/A
	Marked Crosswalk 1 Width (in)	144		Marked Crosswalk 2 Width (in)	N/A
Yes	Ramp Inside Crosswalk 1	Yes	Yes	Ramp Inside Crosswalk 2	N/A
	Crossing 1 Slope (%)	1.9		Crossing 2 Slope (%)	N/A
	Crossing 1 Cross Slope (%)	0.5		Crossing 2 Cross Slope (%)	N/A
Yes	Gutter Ponding	No	No	Curb Slope	13.9
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	N/A
No	Gutter Run Slope (%)	8.5		Road Cross Slope (%)	N/A
Yes	Gutter Cross Slope (%)	0.5			
Yes	Overall Surface Condition:	Acceptable	No	Perp Joint Present	No
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	N/A		Replace Spandrel?	N/A

