




# Access Compliance Report Public Rights-of-Way (Curb Ramps)



**Main Street:** SNOW\_BUSH\_ST      **Cross Street:** CLARIN\_ST      **Location:** NW

**ADA ID:** RPRK211028134507      **Ramp Type:** Type 1 - Perpendicular      **Initial Pass/Fail:** Fail      **Overall Compliance:** No      **Severity Score:** 16

**Codes/Mitigation Info/Possible Solution**      **Field Measurements/Component Compliance**



**Possible Solutions:**  
Remove & Replace Entire Ramp.

**Surveyor Notes:**  
N/A

**OC Std/PROW:**  
R304.2.2, R204.3, R304.5.3, STD 1115

**Total Cost:** \$ 3080

**Parcel ID Number:** 741-281-02  
**Ramp Island Or Median:** None  
**Ramp Orientation:** NonDiag  
**Google Street View Link:**  
[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.54120708,-117.64912576](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.54120708,-117.64912576)

**Street 1 Name:** SNOW\_BUSH\_ST  
**Stop Condition-Street 1:** StopSign  
**Street 2 Name:** CLARIN\_ST  
**Stop Condition-Street 2:** N/A

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	65	N/A	Flare Type LT	
Yes	Ramp Width (in)	48			N/A
No	Ramp Run Slope (%)	9.5	N/A	Flare Slope LT (%)	N/A
No	Ramp Cross Slope (%)	4.2	N/A	Flare Traversable LT	N/A
N/A	Landing Present	N/A	N/A	Flare Type RT	
N/A	Landing Length (in)	N/A			N/A
N/A	Landing Width (in)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Landing Run Slope (%)	N/A	N/A	Flare Traversable RT	N/A
N/A	Landing Cross Slope (%)	N/A	N/A	DWS Provided	N/A
N/A	Landing Movement Obstructed?	N/A	N/A	DWS Contrast	N/A
	Landing Movement Type	N/A	N/A	DWS Length (in)	N/A
N/A	Landing Shared	N/A	N/A	DWS Full Width	N/A
N/A	Clear Space	N/A	N/A	DWS Offset Left (in)	N/A
N/A	Clear Space To Crosswalk (in)	N/A	N/A	DWS Offset Right (in)	N/A
N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	N/A
	Crossing 1 Direction	E		Crossing 2 Direction	N/A
	Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A
N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp Inside Crosswalk 2	N/A
	Crossing 1 Slope (%)	2.8		Crossing 2 Slope (%)	N/A
	Crossing 1 Cross Slope (%)	4.5		Crossing 2 Cross Slope (%)	N/A
N/A	Gutter Ponding	N/A	No	Curb Slope	8.2
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	N/A
N/A	Gutter Run Slope (%)	N/A		Road Cross Slope (%)	N/A
N/A	Gutter Cross Slope (%)	N/A			
Yes	Overall Surface Condition:	Acceptable	No	Perp Joint Present	No
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	N/A		Replace Spandrel?	N/A

**Obstruction and Utility Measurement/Component Compliance**

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A

