



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: ANTONIO_PKWY Cross Street: SWEETWATER Location: N

ADA ID: RPRK211028172433 Ramp Type: Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 20

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:
Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.

Surveyor Notes:
 N/A

OC Std/PROW:
 R304.2.2, R304.2.1, R305, R304.5.4, STD 1115

Total Cost: \$ 6412

Parcel ID Number: 787-271-07
 Ramp Island Or Median: None
 Ramp Orientation: Diag
 Google Street View Link:
http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.58799317,-117.62955879

Street 1 Name: ANTONIO_PKWY
 Stop Condition-Street 1: Signal
 Street 2 Name: SWEETWATER
 Stop Condition-Street 2: Signal

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	99	N/A	Flare Type LT	
Yes	Ramp Width (in)	48		Flare Slope LT (%)	9.7
Yes	Ramp Run Slope (%)	7	N/A	Flare Traversable LT	No
Yes	Ramp Cross Slope (%)	0.9	N/A	Flare Type RT	
N/A	Landing Present	Yes		Flare Slope RT (%)	6.5
N/A	Landing Length (in)	36		Flare Traversable RT	No
Yes	Landing Width (in)	48	N/A	DWS Provided	No
Yes	Landing Run Slope (%)	0.7	N/A	DWS Contrast	N/A
Yes	Landing Cross Slope (%)	1.4	No	DWS Length (in)	N/A
N/A	Landing Movement Obstructed?	No	N/A	DWS Full Width	N/A
	Landing Movement Type	N/A	N/A	DWS Offset Left (in)	N/A
N/A	Landing Shared	Yes	N/A	DWS Offset Right (in)	N/A
Yes	Clear Space	Yes	N/A	Marked Crosswalk 1	Yes
Yes	Clear Space To Crosswalk (in)	48	N/A	Crossing 1 Direction	SW
N/A	Marked Crosswalk 1	Yes	N/A	Crossing 2 Direction	SE
	Crossing 1 Width (in)	144		Marked Crosswalk 2 Width (in)	144
Yes	Ramp Inside Crosswalk 1	Yes	Yes	Ramp Inside Crosswalk 2	Yes
	Crossing 1 Slope (%)	2.1		Crossing 1 Slope (%)	7
	Crossing 1 Cross Slope (%)	0.5		Crossing 2 Slope (%)	2.1
Yes	Gutter Ponding	No	No	Curb Slope	6.8
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	0.7
No	Gutter Run Slope (%)	11.7		Road Cross Slope (%)	2.5
Yes	Gutter Cross Slope (%)	0.4			
Yes	Overall Surface Condition: Acceptable		Yes	Perp Joint Present	Yes
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	N/A		Replace Spandrel?	N/A

