



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: **N/A** Cross Street: **ETHEREAL_RD** Location: **W**

ADA ID: **RPRK211104122932** Ramp Type: **Type 4 - Parallel** Initial Pass/Fail: **Fail** Overall Compliance: **No** Severity Score: **19**

Codes/Mitigation Info/Possible Solution **Field Measurements/Component Compliance**



Possible Solutions:
Remove & Replace Entire Ramp.

Surveyor Notes:
N/A

OC Std/PROW:
R204.3, R304.5.1, R304.3.2, STD 1115

Total Cost: **\$ 2000**

Parcel ID Number: **741-284-02**
 Ramp Island Or Median: **None**
 Ramp Orientation: **NonDiag**
 Google Street View Link:
http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.53953175,-117.64386727

Street 1 Name: **N/A**
 Stop Condition-Street 1: **NoControl**
 Street 2 Name: **ETHEREAL_RD**
 Stop Condition-Street 2: **N/A**

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	110	N/A	Ramp Length RT (in)	-9999
No	Ramp Width LT (in)	45	N/A	Ramp Width RT (in)	-9999
No	Ramp Run Slope LT (%)	10.1	N/A	Ramp Run Slope RT (%)	-9999
Yes	Ramp Cross Slope LT (%)	1.2	N/A	Ramp Cross Slope RT (%)	-9999
N/A	Landing Present	N/A	N/A	DWS Provided	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Contrast	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing Run Slope (%)	N/A	N/A	DWS Full Width	N/A
N/A	Landing Cross Slope (%)	N/A		DWS Offset Type	N/A
N/A	Landing Movement Obstructed?	N/A	N/A	DWS Offset Left (in)	N/A
	Landing Movement Type	N/A	N/A	DWS Offset Right (in)	N/A
N/A	Landing Shared	N/A			
N/A	Clear Space	N/A			
N/A	Clear Space To Crosswalk (in)	N/A			
N/A	Marked Crosswalk 1	Yes	N/A	Marked Crosswalk 2	N/A
	Crossing 1 Direction	N		Crossing 2 Direction	N/A
N/A	Marked Crosswalk 1 Width (in)	56		Marked Crosswalk 2 Width (in)	N/A
N/A	Ramp Inside Crosswalk 1	Yes	N/A	Ramp Inside Crosswalk 2	N/A
	Crossing 1 Slope (%)	2.9		Crossing 2 Slope (%)	N/A
	Crossing 1 Cross Slope (%)	4.7		Crossing 2 Cross Slope (%)	N/A
N/A	Gutter Ponding	N/A	N/A	Curb Slope	8.9
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	N/A
N/A	Gutter Run Slope (%)	N/A		Road Cross Slope (%)	N/A
N/A	Gutter Cross Slope (%)	N/A	No	Perpendicular Joint Present	No
Yes	Overall Surface Condition	Acceptable		Spandrel Present?	No
	Cross Gutter Present?	No		Replace Spandrel?	N/A
	Replace Cross Gutter?	N/A			

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A

