



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: SIENNA_PKWY Cross Street: ETHEREAL_RD Location: E

ADA ID: RPRK211115123018 Ramp Type: Type 4 - Parallel Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 15

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Entire Ramp. Remove & Replace Gutter.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, R304.2.1, R305, R304.5.4, STD 1115

Total Cost: \$ 2252

Parcel ID Number 741-361-61
Ramp Island Or Median None
Ramp Orientation NonDiag
Google Street View Link:

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.53956742,-117.64338789

Street 1 Name SIENNA_PKWY
Stop Condition-Street 1 NoControl
Street 2 Name ETHEREAL_RD
Stop Condition-Street 2 N/A

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	-9999	N/A	Ramp Length RT (in)	82
N/A	Ramp Width LT (in)	-9999	Yes	Ramp Width RT (in)	49
N/A	Ramp Run Slope LT (%)	-9999	Yes	Ramp Run Slope RT (%)	6.8
N/A	Ramp Cross Slope LT (%)	-9999	Yes	Ramp Cross Slope RT (%)	0.6
N/A	Landing Present	Yes	No	DWS Provided	No
N/A	Landing Length (in)	52	N/A	DWS Contrast	N/A
Yes	Landing Width (in)	49	N/A	DWS Length (in)	N/A
Yes	Landing Run Slope (%)	1.2	N/A	DWS Full Width	N/A
Yes	Landing Cross Slope (%)	0.8		DWS Offset Type	N/A
N/A	Landing Movement Obstructed?	Yes	N/A	DWS Offset Left (in)	N/A
	Landing Movement Type	Curb	N/A	DWS Offset Right (in)	N/A
N/A	Landing Shared	No			
N/A	Clear Space	N/A			
N/A	Clear Space To Crosswalk (in)	N/A			
N/A	Marked Crosswalk 1	Yes	N/A	Marked Crosswalk 2	N/A
	Crossing 1 Direction	N		Crossing 2 Direction	N/A
	Marked Crosswalk 1 Width (in)	144		Marked Crosswalk 2 Width (in)	N/A
Yes	Ramp Inside Crosswalk 1	Yes	N/A	Ramp Inside Crosswalk 2	N/A
	Crossing 1 Slope (%)	3.6		Crossing 2 Slope (%)	N/A
	Crossing 1 Cross Slope (%)	1.1		Crossing 2 Cross Slope (%)	N/A
Yes	Gutter Ponding	No	No	Curb Slope	18.7
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	N/A
No	Gutter Run Slope (%)	9.6		Road Cross Slope (%)	N/A
Yes	Gutter Cross Slope (%)	1.8	Yes	Perpendicular Joint Present	Yes
Yes	Overall Surface Condition	Acceptable			
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	N/A		Replace Spandrel?	N/A

