

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data


Main Street: SENDERO WAY **Cross Street: SENDERO WAY** Location: NW ADA ID: RPRK211117125104 Ramp Type: No Ramp Initial Pass/Fail: N/A **Overall Compliance: No Severity Score:** 100

N/A

N/A

**Codes/Mitigation Info/Possible Solution** 

**Field Measurements/Component Compliance** 



Parcel ID Number 741-581-79 Street 1 Name SENDERO WAY Ramp Island Or Median N/A Stop Condition-Street 1 Ramp Orientation Street 2 Name SENDERO\_WAY Google Street View Link: Stop Condition-Street 2

http://www.google.com/maps/@?api=1&map\_action=pano&viewpoint=33.5273647,-117.62335635

Compliance	Description	Data	Compliance	Description	
,					

