



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: RISILLA_ST		Cross Street: RISILLA_ST		Location:	S
ADA ID: RPRK211119151201	Ramp Type: No Ramp	Initial Pass/Fail: N/A	Overall Compliance: No	Severity Score:	100
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		



Possible Solutions:

Provide Curb Ramp

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost: \$ 3080

Parcel ID Number 755-462-29

Ramp Island Or Median N/A

Ramp Orientation N/A

Google Street View Link:

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.53844878,-117.60167773

Street 1 Name RISILLA_ST

Stop Condition-Street 1 N/A

Street 2 Name RISILLA_ST

Stop Condition-Street 2 N/A

Compliance	Description	Data	Compliance	Description	Data
------------	-------------	------	------------	-------------	------

