

# Access Compliance Report Public Rights-of-Way (Curb Ramps)

Main Street: **SUERTE\_ST** Cross Street: **MEDANO\_ST** Location: **S**

ADA ID: **RPRK211124134801** Ramp Type: **Type 1 - Perpendicular** Initial Pass/Fail: **Pass** Overall Compliance: **No** Severity Score: **5**

### Codes/Mitigation Info/Possible Solution

### Field Measurements/Component Compliance



Possible Solutions:  
**Remove & Replace Curb Slope. Remove & Replace Gutter.**

Surveyor Notes:  
**N/A**

OC Std/PROW:  
**R304.2.2, R304.5.4, STD 1115**

Total Cost: **\$ 504**

Parcel ID Number: **125-271-14**  
Ramp Island Or Median: **None**  
Ramp Orientation: **NonDiag**  
Google Street View Link:  
[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.54803357,-117.59906202](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.54803357,-117.59906202)

Street 1 Name: **SUERTE\_ST**  
Stop Condition-Street 1: **NoControl**  
Street 2 Name: **MEDANO\_ST**  
Stop Condition-Street 2: **N/A**

### Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	153	N/A	Flare Type LT	
Yes	Ramp Width (in)	60		Flare Slope LT (%)	18.6
Yes	Ramp Run Slope (%)	4	N/A	Flare Traversable LT	No
Yes	Ramp Cross Slope (%)	1.2	N/A	Flare Type RT	
N/A	Landing Present	Yes		Flare Slope RT (%)	8.6
N/A	Landing Length (in)	60		Flare Traversable RT	No
Yes	Landing Width (in)	66	N/A	DWS Provided	Yes
Yes	Landing Run Slope (%)	0.7	N/A	DWS Contrast	Yes
Yes	Landing Cross Slope (%)	1	Yes	DWS Length (in)	36
N/A	Landing Movement Obstructed?	No	Yes	DWS Full Width	Yes
	Landing Movement Type	N/A	Yes	DWS Offset Left (in)	0
N/A	Landing Shared	No	Yes	DWS Offset Right (in)	N/A
N/A	Clear Space	N/A	N/A	Marked Crosswalk 1	Yes
N/A	Clear Space To Crosswalk (in)	N/A	Yes	Marked Crosswalk 2	N/A
N/A	Marked Crosswalk 1	Yes	N/A	Crossing 1 Direction	N
	Crossing 1 Direction	N		Crossing 2 Direction	N/A
	Marked Crosswalk 1 Width (in)	144		Marked Crosswalk 2 Width (in)	N/A
Yes	Ramp Inside Crosswalk 1	Yes	Yes	Ramp Inside Crosswalk 2	N/A
	Crossing 1 Slope (%)	5.7		Crossing 2 Slope (%)	N/A
	Crossing 1 Cross Slope (%)	3.2		Crossing 2 Cross Slope (%)	N/A
Yes	Gutter Ponding	No	No	Curb Slope	7.7
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	N/A
No	Gutter Run Slope (%)	6.4		Road Cross Slope (%)	N/A
Yes	Gutter Cross Slope (%)	2.6			
Yes	Overall Surface Condition: <b>Acceptable</b>		Yes	Perp Joint Present	Yes
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	N/A		Replace Spandrel?	N/A

