

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: N/A **Cross Street: AIROSO_ST** Location: SE

ADA ID: RPRK211130123107 Ramp Type: Type 4 - Parallel **Initial Pass/Fail: Pass Overall Compliance: No Severity Score:** 5

Codes/Mitigation Info/Possible Solution

| | Codes/Mitigation into/ |
|---|------------------------|
| Minosoo Sal | |
| SUZIUZ SI | |
| A PARTIE OF THE | |
| | |

Restripe Crosswalk. Remove & Replace Gutter.

Surveyor Notes:

Possible Solutions:

N/A

OC Std/PROW:

R207.1, R304.5.4, STD 1115

Total Cost: 4252

| Parcel ID Number | 125-211-60 | , |
|--------------------------|------------|---|
| Ramp Island Or Median | None | , |
| Ramp Orientation | Diag | ; |
| Google Street View Link: | | ; |

N/A Street 1 Name Stop Condition-Street 1 StopSign Street 2 Name AIROSO_ST Stop Condition-Street 2 StopSign

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.54837841,-117.5969521

Obstruction and Utility Measurement/Component Compliance

| Com | pliance Description | Data | Compliance Description | Data |
|-----|------------------------|------|------------------------|------|
| Yes | Obstructions Present? | No | N/A Utilities Present? | No |
| | Obstruction Types | N/A | Utility Types | |
| | Obstruction Dimensions | N/A | l | N/A |



| Field Measurements/Component Compliance | | | | | | | |
|---|-----|---------------------------------------|------|------------------------|----------|------------------------|--------|
| | Com | Compliance Description | | Compliance Description | | Description | Data |
| | N/A | Ramp Length LT (in) | 124 | N/A | Ramp L | ength RT (in) | 114 |
| | Yes | Ramp Width LT (in) | 53 | Yes | Ramp V | /idth RT (in) | 53 |
| | Yes | Ramp Run Slope LT (%) | 1.2 | Yes | Ramp R | tun Slope RT (%) | 5.2 |
| | Yes | Ramp Cross Slope LT (%) | 0.8 | Yes | Ramp C | ross Slope RT (%) | 0.4 |
| | N/A | Landing Present | Yes | Yes | DWS Pr | ovided | Yes |
| | N/A | Landing Length (in) | 53 | Yes | DWS C | ontrast | Yes |
| | Yes | Landing Width (in) | 60 | Yes | DWS Le | ength (in) | 36 |
| | Yes | Landing Run Slope (%) | 0.4 | Yes | DWS Fu | ıll Width | Yes |
| | Yes | Landing Cross Slope (%) | 0 | | DWS O | fset Type | Single |
| | N/A | Landing Movement Obstructed? | No | Yes | DWS O | ffset Left (in) | 0 |
| | | Landing Movement Type | Curb | Yes | DWS O | ffset Right (in) | N/A |
| | N/A | Landing Shared | No | | | | |
| | Yes | Clear Space | Yes | | | | |
| | Yes | Clear Space To Crosswalk (in) | 48 | | | | |
| 2 | N/A | Marked Crosswalk 1 | Yes | N/A | Marked | Crosswalk 2 | Yes |
| | | Crossing 1 Direction | N | | Crossin | g 2 Direction | W |
| A | | Marked Crosswalk 1 Width (in) | 144 | | Marked | Crosswalk 2 Width (in) | 144 |
| n | No | Ramp Inside Crosswalk 1 | No | No | Ramp Ir | nside Crosswalk 2 | No |
| T | | Crossing 1 Slope (%) | 3 | | Crossin | g 2 Slope (%) | 1.6 |
| n | | Crossing 1 Cross Slope (%) | 3.3 | | Crossin | g 2 Cross Slope (%) | 0.1 |
| | Yes | Gutter Ponding | No | Yes | Curb Slo | оре | 5.5 |
| | Yes | Gutter Lip Height (in) | 0 | | Road R | un Slope (%) | 0 |
| _ | No | Gutter Run Slope (%) | 8.9 | | Road C | ross Slope (%) | 9.8 |
| <u>a</u> | Yes | Gutter Cross Slope (%) | 0 | Yes | Perpend | licular Joint Present | Yes |
| 0 | Yes | es Overall Surface Condition Acceptat | | | | | |
| | | Cross Gutter Present? | No | | Spandr | el Present? | No |
| A | | Replace Cross Gutter? | N/A | | Replace | e Spandrel? | N/A |
| | 1 | | | | | | |