



# Access Compliance Report Public Rights-of-Way (Curb Ramps)



|                                         |                                     |                                         |                               |                           |
|-----------------------------------------|-------------------------------------|-----------------------------------------|-------------------------------|---------------------------|
| Main Street: <b>NARROW_CANYON_RD</b>    |                                     | Cross Street: <b>N/A</b>                |                               | Location: <b>E</b>        |
| ADA ID: <b>RPRK211202121954</b>         | Ramp Type: <b>Type 4 - Parallel</b> | Initial Pass/Fail: <b>Pass</b>          | Overall Compliance: <b>No</b> | Severity Score: <b>25</b> |
| Codes/Mitigation Info/Possible Solution |                                     | Field Measurements/Component Compliance |                               |                           |



#### Possible Solutions:

**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.**

#### Surveyor Notes:

**N/A**

#### OC Std/PROW:

**R204.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R305, R304.5.4, STD 1115**

Total Cost: \$ **4252**

|                          |                   |                         |                         |
|--------------------------|-------------------|-------------------------|-------------------------|
| Parcel ID Number         | <b>741-391-55</b> | Street 1 Name           | <b>NARROW_CANYON_RD</b> |
| Ramp Island Or Median    | <b>None</b>       | Stop Condition-Street 1 | <b>NoControl</b>        |
| Ramp Orientation         | <b>Diag</b>       | Street 2 Name           | <b>N/A</b>              |
| Google Street View Link: |                   | Stop Condition-Street 2 | <b>NoControl</b>        |

[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.54004981,-117.64701705](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.54004981,-117.64701705)

#### Obstruction and Utility Measurement/Component Compliance

| Compliance | Description            | Data       | Compliance | Description        | Data       |
|------------|------------------------|------------|------------|--------------------|------------|
| <b>Yes</b> | Obstructions Present?  | <b>No</b>  | <b>N/A</b> | Utilities Present? | <b>No</b>  |
|            | Obstruction Types      | <b>N/A</b> |            | Utility Types      |            |
|            | Obstruction Dimensions | <b>N/A</b> |            |                    | <b>N/A</b> |



| Compliance | Description                   | Data              | Compliance | Description                   | Data       |
|------------|-------------------------------|-------------------|------------|-------------------------------|------------|
| <b>N/A</b> | Ramp Length LT (in)           | <b>137</b>        | <b>N/A</b> | Ramp Length RT (in)           | <b>142</b> |
| <b>Yes</b> | Ramp Width LT (in)            | <b>90</b>         | <b>Yes</b> | Ramp Width RT (in)            | <b>90</b>  |
| <b>Yes</b> | Ramp Run Slope LT (%)         | <b>5.8</b>        | <b>Yes</b> | Ramp Run Slope RT (%)         | <b>0.8</b> |
| <b>Yes</b> | Ramp Cross Slope LT (%)       | <b>1.3</b>        | <b>Yes</b> | Ramp Cross Slope RT (%)       | <b>0.3</b> |
| <b>N/A</b> | Landing Present               | <b>No</b>         | <b>No</b>  | DWS Provided                  | <b>No</b>  |
| <b>N/A</b> | Landing Length (in)           | <b>N/A</b>        | <b>N/A</b> | DWS Contrast                  | <b>N/A</b> |
| <b>No</b>  | Landing Width (in)            | <b>N/A</b>        | <b>N/A</b> | DWS Length (in)               | <b>N/A</b> |
| <b>No</b>  | Landing Run Slope (%)         | <b>N/A</b>        | <b>N/A</b> | DWS Full Width                | <b>N/A</b> |
| <b>No</b>  | Landing Cross Slope (%)       | <b>N/A</b>        |            | DWS Offset Type               | <b>N/A</b> |
| <b>N/A</b> | Landing Movement Obstructed?  | <b>No</b>         | <b>N/A</b> | DWS Offset Left (in)          | <b>N/A</b> |
|            | Landing Movement Type         | <b>Curb</b>       | <b>N/A</b> | DWS Offset Right (in)         | <b>N/A</b> |
| <b>N/A</b> | Landing Shared                | <b>N/A</b>        |            |                               |            |
| <b>N/A</b> | Clear Space                   | <b>Yes</b>        |            |                               |            |
| <b>N/A</b> | Clear Space To Crosswalk (in) | <b>48</b>         |            |                               |            |
| <b>N/A</b> | Marked Crosswalk 1            | <b>No</b>         | <b>N/A</b> | Marked Crosswalk 2            | <b>No</b>  |
|            | Crossing 1 Direction          | <b>NW</b>         |            | Crossing 2 Direction          | <b>SW</b>  |
| <b>N/A</b> | Marked Crosswalk 1 Width (in) | <b>N/A</b>        |            | Marked Crosswalk 2 Width (in) | <b>N/A</b> |
| <b>N/A</b> | Ramp Inside Crosswalk 1       | <b>N/A</b>        | <b>N/A</b> | Ramp Inside Crosswalk 2       | <b>N/A</b> |
|            | Crossing 1 Slope (%)          | <b>1.2</b>        |            | Crossing 2 Slope (%)          | <b>2.1</b> |
|            | Crossing 1 Cross Slope (%)    | <b>1.2</b>        |            | Crossing 2 Cross Slope (%)    | <b>1.7</b> |
| <b>Yes</b> | Gutter Ponding                | <b>No</b>         | <b>Yes</b> | Curb Slope                    | <b>3.5</b> |
| <b>Yes</b> | Gutter Lip Height (in)        | <b>0</b>          |            | Road Run Slope (%)            | <b>2.4</b> |
| <b>No</b>  | Gutter Run Slope (%)          | <b>7.6</b>        |            | Road Cross Slope (%)          | <b>0.9</b> |
| <b>No</b>  | Gutter Cross Slope (%)        | <b>3.8</b>        | <b>No</b>  | Perpendicular Joint Present   | <b>No</b>  |
| <b>Yes</b> | Overall Surface Condition     | <b>Acceptable</b> |            |                               |            |
|            | Cross Gutter Present?         | <b>No</b>         |            | Spandrel Present?             | <b>No</b>  |
|            | Replace Cross Gutter?         | <b>N/A</b>        |            | Replace Spandrel?             | <b>N/A</b> |