




Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: BLUME_DR		Cross Street: BLUME_DR		Location:	S
ADA ID: RPRK211208131049	Ramp Type: No Ramp	Initial Pass/Fail: N/A	Overall Compliance: No	Severity Score:	100
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		

		Possible Solutions: Provide Curb Ramp		<table><tr><th>Compliance</th><th>Description</th><th>Data</th><th>Compliance</th><th>Description</th><th>Data</th></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td></tr></table>		Compliance	Description	Data	Compliance	Description	Data																								
Compliance	Description	Data	Compliance	Description	Data																														
Surveyor Notes: N/A																																			
OC Std/PROW: STD 1115																																			
Total Cost:		\$	3080																																
Parcel ID Number	086-161-01	Street 1 Name	BLUME_DR																																
Ramp Island Or Median	N/A	Stop Condition-Street 1	N/A																																
Ramp Orientation	N/A	Street 2 Name	BLUME_DR																																
Google Street View Link:		Stop Condition-Street 2	N/A																																
http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.78301377,-118.08016333																																			
