

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Main Street: BLUME\_DR **Cross Street: BLUME\_DR** Location:

**Overall Compliance: No** ADA ID: RPRK211208132103 Ramp Type: No Ramp Initial Pass/Fail: N/A **Severity Score:** 100

3080

N/A

N/A

## **Codes/Mitigation Info/Possible Solution**

**Field Measurements/Component Compliance** 



Possible Solutions:

**Provide Curb Ramp** 

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost:

Parcel ID Number Ramp Island Or Median Ramp Orientation Google Street View Link:

N/A

086-162-17 Street 1 Name **BLUME DR** Stop Condition-Street 1

Street 2 Name BLUME\_DR Stop Condition-Street 2

http://www.google.com/maps/@?api=1&map\_action=pano&viewpoint=33.78328808,-118.07716882

Compliance	Description	Data	<ul> <li>Compliance</li> </ul>	Description	<u>Data</u>

