

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

Main Street: BLUME DR **Cross Street: BLUME\_DR** Location: ADA ID: RPRK211208132326 Ramp Type: No Ramp Initial Pass/Fail: N/A **Overall Compliance: No Severity Score:** 100

> **Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance**

> > 3080

N/A

N/A

**BLUME DR** 

BLUME\_DR

Possible Solutions: **Provide Curb Ramp** 

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost:

086-154-11

Street 1 Name

Stop Condition-Street 1

Street 2 Name

Stop Condition-Street 2

http://www.google.com/maps/@?api=1&map\_action=pano&viewpoint=33.78334696,-118.07738626

Compliance Description Data Compliance Description

Parcel ID Number

Ramp Orientation

Ramp Island Or Median

Google Street View Link: