

ADA ID: RPRK211209115549

Access Compliance Report Public Rights-of-Way (Curb Ramps)



100

Main Street: BLUME DR Cross Street: BLUME_DR Location:

> **Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance**

Initial Pass/Fail: N/A

Possible Solutions:

Ramp Type: No Ramp

BLUME DR

Provide Curb Ramp

Surveyor Notes:

N/A

OC Std/PROW:

Compliance Description

Overall Compliance: No

Data Compliance

Description Data

Severity Score:

STD 1115 Total Cost: 3080 Parcel ID Number 086-253-01 Street 1 Name **BLUME DR** Ramp Island Or Median Stop Condition-Street 1 N/A Ramp Orientation Street 2 Name BLUME_DR Google Street View Link: Stop Condition-Street 2 N/A http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.78315258,-118.08087212





