




# Access Compliance Report Public Rights-of-Way (Curb Ramps)



|                                         |                    |                        |                                         |                 |     |
|-----------------------------------------|--------------------|------------------------|-----------------------------------------|-----------------|-----|
| Main Street: BLUME_DR                   |                    | Cross Street: BLUME_DR |                                         | Location:       | S   |
| ADA ID: RPRK211210145412                | Ramp Type: No Ramp | Initial Pass/Fail: N/A | Overall Compliance: No                  | Severity Score: | 100 |
| Codes/Mitigation Info/Possible Solution |                    |                        | Field Measurements/Component Compliance |                 |     |



Possible Solutions:  
**Provide Curb Ramp**

Surveyor Notes:  
**N/A**

OC Std/PROW:  
**STD 1115**

Total Cost: \$ 3080

| Compliance | Description | Data | Compliance | Description | Data |
|------------|-------------|------|------------|-------------|------|
|            |             |      |            |             |      |

|                          |            |                         |          |
|--------------------------|------------|-------------------------|----------|
| Parcel ID Number         | 086-231-02 | Street 1 Name           | BLUME_DR |
| Ramp Island Or Median    | N/A        | Stop Condition-Street 1 | N/A      |
| Ramp Orientation         | N/A        | Street 2 Name           | BLUME_DR |
| Google Street View Link: |            | Stop Condition-Street 2 | N/A      |

[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.78302897,-118.08264895](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.78302897,-118.08264895)

