



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: SANTA_CLARA_AVE **Cross Street: WHEELER_PL** **Location: SE**

ADA ID: RPRK220127121215 **Ramp Type: Type 4 - Parallel** **Initial Pass/Fail: Fail** **Overall Compliance: No** **Severity Score: 16**

Codes/Mitigation Info/Possible Solution **Field Measurements/Component Compliance**



Possible Solutions:
Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:
 N/A

OC Std/PROW:
 R304.3.2, R304.5.3, STD 1115

Total Cost: \$ 4000

Parcel ID Number: 395-272-27
Ramp Island Or Median: None
Ramp Orientation: Diag
Google Street View Link:
http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.7670157,-117.82418133

Street 1 Name: SANTA_CLARA_AVE
Stop Condition-Street 1: NoControl
Street 2 Name: WHEELER_PL
Stop Condition-Street 2: StopSign

Obstruction and Utility Measurement/Component Compliance			
Compliance	Description	Data	Compliance Description
Yes	Obstructions Present?	No	N/A Utilities Present?
	Obstruction Types	N/A	Utility Types
	Obstruction Dimensions	N/A	

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	88	N/A	Ramp Length RT (in)	60
Yes	Ramp Width LT (in)	91	Yes	Ramp Width RT (in)	91
No	Ramp Run Slope LT (%)	9.1	Yes	Ramp Run Slope RT (%)	1.7
Yes	Ramp Cross Slope LT (%)	1.6	No	Ramp Cross Slope RT (%)	3.5
N/A	Landing Present	N/A	N/A	DWS Provided	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Contrast	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing Run Slope (%)	N/A	N/A	DWS Full Width	N/A
N/A	Landing Cross Slope (%)	N/A		DWS Offset Type	N/A
N/A	Landing Movement Obstructed?	N/A	N/A	DWS Offset Left (in)	N/A
	Landing Movement Type	N/A	N/A	DWS Offset Right (in)	N/A
N/A	Landing Shared	N/A			
N/A	Clear Space	Yes			
N/A	Clear Space To Crosswalk (in)	N/A			
N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	No
	Crossing 1 Direction	N		Crossing 2 Direction	W
N/A	Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A
N/A	Ramp Inside Crosswalk 1	N/A	N/A	Ramp Inside Crosswalk 2	N/A
	Crossing 1 Slope (%)	9.1		Crossing 2 Slope (%)	1.7
	Crossing 1 Cross Slope (%)	0.6		Crossing 2 Cross Slope (%)	4.6
N/A	Gutter Ponding	N/A	N/A	Curb Slope	6.6
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	4.4
N/A	Gutter Run Slope (%)	N/A		Road Cross Slope (%)	3.5
N/A	Gutter Cross Slope (%)	N/A	Yes	Perpendicular Joint Present	Yes
Yes	Overall Surface Condition	Acceptable			
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	N/A		Replace Spandrel?	N/A

